



RENAULT

BKI7NHY

report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27 SPORT ENERGY DCI
Colour	Black
Year of manufacture	2017
Top speed	105 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	49.6 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-09-13
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-12
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	32
Total items failed	18

MOT #13 2023-11-10 17:40

MOT test number 153038408772

Result ✓ Passed

Next expiry date 2024-11-12

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #12 2023-10-31 16:35

MOT test number 392677177520

Result ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Tyre not fitted in accordance with side wall instructions incorrect load rating should be a commercial (5.2.3 (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions incorrect load rating should be a commercial (5.2.3 (i))

**MOT #11**

2022-11-11 15:55

MOT test number

344997591454

Result

✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #10**

2022-11-08 17:05

MOT test number

277187088226

Result

✗ Failed

Fail Offside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))



MOT #92021-11-13 10:39

MOT test number423054454926

Result

✓ Passed

- Advice

Offside Front Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge on outer edge (5.2.3 (e))
- Advice

Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge on outer edge (5.2.3 (e))
- Advice

Front plastic undertray / trim is insecure

**MOT #8**

2021-11-11 15:47

MOT test number

253347152291

Result**✗ Failed**

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on outer edge (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front plastic undertray / trim is insecure
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on outer edge (5.2.3 (e))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front day time running light is not working
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #7

2021-07-19 13:35

MOT test number

674234436234

Result**✓ Passed**

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6** 2021-01-20 15:36**MOT test number** 449409155337**Result** ✓ Passed**MOT #5** 2021-01-20 13:12**MOT test number** 675979790292**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**MOT #4** 2020-08-05 08:18**MOT test number** 362054302366**Result** ✓ Passed**MOT #3** 2020-01-26 12:57**MOT test number** 760933558334**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #2** 2019-08-02 10:20**MOT test number** 927760180325**Result** ✓ Passed**MOT #1** 2019-02-04 15:12**MOT test number** 429953923741**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
12 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	12 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	REDACTED
Plate since	2024-03-28
Current registration	REDACTED
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2017-03-23
Last registration	2023-11-10
Complete history	See info



Registration #1	2017-03-23	21 mi
Registration #2	2019-02-04	3.725 mi
Registration #3	2019-08-02	45.953 mi
Registration #4	2020-01-26	84.773 mi
Registration #5	2020-08-05	99.570 mi
Registration #6	2021-01-20	117.629 mi
Registration #7	2021-01-20	117.635 mi
Registration #8	2021-07-19	166.003 mi
Registration #9	2022-01-01	200.000 mi
Registration #10	2022-01-01	200.000 mi
Registration #11	2022-01-01	200.000 mi
Registration #12	2022-01-01	200.000 mi
Registration #13	2022-01-01	200.000 mi
Registration #14	2022-01-01	200.000 mi
Registration #15	2023-11-10	200.000 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4999 mm
Kerb weight	1882 kg
Max. allowed weight	2840 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2

Engine number

C160453