



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SHARAN S TDI (115BHP)
Colour	Blue
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	310 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-15
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	27
Total items failed	20

MOT #21	2023-10-06 13:58
MOT test number	868989406019
Result	✓ Passed
Next expiry date	2024-10-25
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Central Rear 2nd row seat belt stalk outer casing damaged

MOT #20	2023-10-06 09:20
MOT test number	105053832140
Result	✗ Failed
Fail	Central Rear Seat belt buckle damaged 2nd row (7.1.2 (d))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)

**MOT #19**

2022-10-26 15:56

**MOT test number**

667242627389

**Result**

✓ Passed

- Advice** Tyre slightly damaged/cracking or perishing All four tyres are cracking (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Tyre reading 3mm and bald on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre reading 3mm and bald on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre bald on edge (5.2.3 (e))

**MOT #18**

2022-10-24 15:09

**MOT test number**

922753001414

**Result**

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Tyre reading 3mm and bald on edge (5.2.3 (e))
- Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre reading 3mm and bald on edge (5.2.3 (e))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre bald on edge (5.2.3 (e))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Tyre slightly damaged/cracking or perishing All four tyres are cracking (5.2.3 (d) (ii))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #17**

2021-04-06 12:27

**MOT test number**

240612157103

**Result**

✓ Passed

**MOT #16** 2021-03-26 09:12**MOT test number** 719522434986**Result** ✗ Failed**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #15** 2020-07-03 12:40**MOT test number** 397291296260**Result** ✓ Passed**MOT #14** 2020-06-30 08:22**MOT test number** 534751109414**Result** ✗ Failed**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #13** 2019-07-11 11:16**MOT test number** 734247430491**Result** ✓ Passed**MOT #12** 2018-07-02 12:45**MOT test number** 164395754525**Result** ✓ Passed



<b>MOT #11</b>	2018-07-02 09:24
<b>MOT test number</b>	360263631738
<b>Result</b>	✗ Failed
<b>Fail</b>	Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

<b>MOT #10</b>	2017-07-18 08:22
<b>MOT test number</b>	493079118505
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
<b>Advice</b>	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Rear registration plate deteriorated but not likely to be misread (6.3.1d)
<b>Advice</b>	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #9</b>	2016-06-28 11:54
<b>MOT test number</b>	546156449240
<b>Result</b>	✓ Passed
<b>Advice</b>	Engine covers fitted
<b>Advice</b>	Under trays fitted

<b>MOT #8</b>	2016-06-28 10:03
<b>MOT test number</b>	946803229993
<b>Result</b>	✗ Failed
<b>Fail</b>	Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.A.3)
<b>Advice</b>	Engine covers fitted
<b>Advice</b>	Under trays fitted

**MOT #7** 2015-07-03 12:14**MOT test number** 179534785142**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2014-07-11 09:28**MOT test number** 256322494472**Result** ✓ Passed**MOT #5** 2013-07-22 15:17**MOT test number** 415623303221**Result** ✓ Passed**MOT #4** 2012-07-17 10:04**MOT test number** 319989492129**Result** ✓ Passed**MOT #3** 2012-07-16 11:18**MOT test number** 239288092188**Result** ✗ Failed**Fail** Offside Steering rack gaiter split (2.2.D.2d)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Ball joint has excessive play (2.2.B.1f)**MOT #2** 2011-06-30 11:41**MOT test number** 218891381131**Result** ✓ Passed



MOT #1	2011-06-30 11:41
MOT test number	765031781132
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Pass with rectification	Nearside Headlamp aim too high (1.8)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
25 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	25 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>MD08AKV</b>
Plate since	2024-03-28
Current registration	 <b>MD08AKV</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-07-21
Last registration	2023-10-06
Complete history	<a href="#">See info</a>



Registration #1	2008-07-21	17 mi
Registration #2	2011-06-30	31.085 mi
Registration #3	2012-07-16	44.701 mi
Registration #4	2012-07-17	44.717 mi
Registration #5	2013-07-22	60.425 mi
Registration #6	2014-07-11	74.509 mi
Registration #7	2015-07-03	87.570 mi
Registration #8	2016-06-28	97.956 mi
Registration #9	2016-06-28	97.957 mi
Registration #10	2017-07-18	103.978 mi
Registration #11	2018-07-02	107.286 mi
Registration #12	2019-06-28	111.217 mi
Registration #13	2019-06-28	111.217 mi
Registration #14	2019-06-28	111.217 mi
Registration #15	2019-06-28	111.217 mi
Registration #16	2019-06-28	111.217 mi
Registration #17	2019-06-28	111.217 mi
Registration #18	2019-06-28	111.217 mi
Registration #19	2019-06-28	111.217 mi
Registration #20	2019-06-28	111.217 mi
Registration #21	2019-06-28	111.217 mi
Registration #22	2019-06-28	111.217 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1759 mm
Length	4634 mm
Wheel base	2841 mm
Kerb weight	1928 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BVK 025047