



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | MAZDA |
| Model | MX-5 SPORT NAV |
| Colour | Red |
| Year of manufacture | 2016 |
| Top speed | 133 mph |
| 0 - 60 mph | 7.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 158 BHP |
| Max. torque | 200 Nm at 4.600 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 30.4 mpg |
| Consumption extra urban | 51.4 mpg |
| Consumption combined | 40.9 mpg |
| CO2 emission | 161 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-15 |
| Pictures | 11 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-09 |
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 11 |
| Total items failed | 0 |

| | |
|------------------|--|
| MOT #5 | 2023-10-10 13:31 |
| MOT test number | 367102815980 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-09 |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Nail in tyre |
| Advice | Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| | |
|-----------------|------------------|
| MOT #4 | 2022-08-22 15:45 |
| MOT test number | 528240194638 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #3 | 2021-08-21 07:53 |
| MOT test number | 239624139265 |
| Result | ✓ Passed |



| | |
|-----------------|---|
| MOT #2 | 2020-08-29 11:12 |
| MOT test number | 803907304752 |
| Result | ✓ Passed |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #1 | 2019-08-21 08:22 |
| MOT test number | 461787514003 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
9 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 307 |
| MOT expiry date | 9 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | NU66ZCL |
| Plate since | 2019-09-29 |
| Current registration | NU66ZCL |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2016-11-30 |
| Last registration | 2023-10-10 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2016-11-30 | 7 mi |
| Registration #2 | 2019-08-21 | 13.910 mi |
| Registration #3 | 2020-08-29 | 15.249 mi |
| Registration #4 | 2021-08-21 | 16.694 mi |
| Registration #5 | 2022-08-29 | 18.143 mi |
| Registration #6 | 2023-08-29 | 19.592 mi |
| Registration #7 | 2023-10-10 | 20.041 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 84% |
| Children | 80% |
| Pedestrian | 93% |
| Safety systems | 64% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1735 mm |
| Height | 1230 mm |
| Length | 3915 mm |
| Wheel base | 2310 mm |
| Kerb weight | 1000 kg |
| Max. allowed weight | 1260 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | PE 30865366 |