



MP53PBF

report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE CLASSIC
Colour	Blue
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	325 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg







Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #20	2020-09-16 11:27
MOT test number	347129615763
Result	✓ Passed
Next expiry date	2021-10-08
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on the inner edge of the tread (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on the inner edge of the tread (5.2.3 (e))

MOT #19	2019-09-09 15:01
MOT test number	628570531865
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Under trays and engine cover fitted obscuring some components
Advice	Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

MOT #18	2019-09-09 11:24
MOT test number	554966070611
Result	✗ Failed
Fail	Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Under trays and engine cover fitted obscuring some components
Advice	Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

**MOT #17**

2018-10-03 10:25

MOT test number

336800725527

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both poor condition (1.1.14 (a) (ii))

Advice Ns and os sills corroding

Advice Nearside Rear parking brake poor effort

Minor Windscreen wiper blade defective both slight smearing (3.4 (b) (i))

Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #16

2018-10-02 12:04

MOT test number

769180722901

Result

✗ Failed

Minor Windscreen wiper blade defective both slight smearing (3.4 (b) (i))

Fail Front Exhaust has a major leak of exhaust gases weld position at flexi section (6.1.2 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Rear Service brake lagging in operation (1.2.1 (d))

Advice Rear Brake pad(s) wearing thin and poor condition (possible overheating) (1.1.13 (a) (ii))

Fail Offside Rear Brake lever has abnormal movement of levers indicating excessive wear or maladjustment caliper parking brake mechanism (1.1.15 (f))

Advice Nearside Rear parking brake poor effort

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both poor condition (1.1.14 (a) (ii))

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Advice Ns and os sills corroding

**MOT #15**

2017-10-04 08:14

MOT test number

251290146453

Result

✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both worn (3.5.1i)**Advice** Rear Brake pipe slightly corroded both (3.6.B.2c)**Advice** Ns and os sills corroding**Advice** Oil leak**MOT #14**

2016-09-30 13:57

MOT test number

796161191997

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both worn (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Oil leak**MOT #13**

2016-09-30 09:31

MOT test number

136647126886

Result

✗ Failed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both worn (3.5.1i)**Advice** Oil leak**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Rear wheel bearing rough when rotated (2.6.1)

**MOT #12** 2015-10-09 11:28**MOT test number** 265558788246**Result** ✓ Passed**Advice** Os headlamp aim set to lower limit**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Advice** All 4 brake discs poor condition from corrosion**MOT #11** 2015-10-09 10:50**MOT test number** 754890864935**Result** ✗ Failed**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Os headlamp aim set to lower limit**Fail** Offside Rear Anti-roll bar rubber mounting deteriorated resulting in excessive movement D bush (2.4.G.2)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Anti-roll bar rubber mounting deteriorated resulting in excessive movement D bush (2.4.G.2)**Advice** All 4 brake discs poor condition from corrosion**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #10** 2014-10-09 14:58**MOT test number** 569822884259**Result** ✓ Passed

**MOT #9** 2014-10-02 11:23**MOT test number** 227205674223**Result** ✗ Failed**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Bonnet catches stiff**Notice** Ignition barrel stiff**Notice** Ns and os headlamp aims set to lower limits**Notice** Vehicle struggled to pass smoke test**MOT #8** 2013-09-18 15:37**MOT test number** 797501563254**Result** ✓ Passed**MOT #7** 2012-09-26 12:03**MOT test number** 718770672283**Result** ✓ Passed**MOT #6** 2011-09-09 12:00**MOT test number** 376592751450**Result** ✓ Passed**MOT #5** 2010-10-02 11:53**MOT test number** 422185970271**Result** ✓ Passed**MOT #4** 2009-09-09 10:33**MOT test number** 701782259207**Result** ✓ Passed



MOT #3	2008-08-30 11:34
MOT test number	360243948263
Result	✓ Passed
MOT #2	2007-09-17 10:01
MOT test number	364270367460
Result	✓ Passed
MOT #1	2006-09-27 14:06
MOT test number	323310776495
Result	✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-09-25
Last registration	2020-09-16
Complete history	See info



Registration #1	2003-09-25	29 mi
Registration #2	2006-09-27	52.922 mi
Registration #3	2007-09-17	64.213 mi
Registration #4	2008-08-30	75.392 mi
Registration #5	2009-09-09	85.658 mi
Registration #6	2010-10-02	95.361 mi
Registration #7	2011-09-09	98.562 mi
Registration #8	2012-09-26	104.859 mi
Registration #9	2013-09-18	110.497 mi
Registration #10	2014-10-02	114.862 mi
Registration #11	2014-10-09	114.862 mi
Registration #12	2015-09-29	115.277 mi
Registration #13	2016-09-29	115.277 mi
Registration #14	2017-09-29	115.277 mi
Registration #15	2018-09-29	115.277 mi
Registration #16	2019-09-29	115.277 mi
Registration #17	2020-09-16	115.277 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	0310160756046B