





report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 GT COUPE
Colour	White
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	185 Nm at 4.800 rpm
Cylinders	4
Fuel type	Petrol



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-22

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT #20	2021-05-26 14:46
MOT test number	965130307169
Result	✓ Passed
Next expiry date	2022-05-25
Advice Surface corrosion underneath the car	

MOT #19	2021-05-26 12:56
MOT test number	743329074669
Result	× Failed
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b)	(ii))
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b	o) (ii))
Advice Surface corrosion underneath the car	

MOT #18		2020-06-16 13:20
MOT test	number	336030462531
Result		✓ Passed
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or ligh	nt sources (4.7.1
Advice	Slight damage to n/s/f wing and rear	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	General vehicle corrosion underside of vehicle	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #17 2019-06-10 11:16 **MOT** test number 558918634014 Result ✓ Passed **Advice** Front Coil spring corroded (5.3.1 (b) (i)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Rear body damage **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #16 2018-06-25 10:59 **MOT** test number 260202852830 Result ✓ Passed Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Registration plate deteriorated but not likely to be misread front and rear (0.1 (b)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Rear body damage **Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15

MOT test number

Result


Advice Rear damage

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 4/12



report date: 2024-03-28



2016-06-09 08:54
811612008588
🗙 Failed


MOT #12		2015-06-12 11:34
MOT test	number	338713465172
Result		✓ Passed
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	N/s/r bumper end insecure	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #11		2014-06-27 12:31
MOT test	number	539928074144
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Exhaust rusty	

CarCheck.co.uk page 5/12



report date: 2024-03-28



MOT #9		2013-06-14 12:01
MOT test	number	888105763149
Result		✓ Passed
Notice Advice	Exhaust mount damaged Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #8	2013-06-13 16:13
MOT test number	436184663195
Result	× Failed
Notice Exhaust mount damaged	
Fail Nearside Front wheel bearing has excessive play (2.5.A.3c)	
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #7		2012-06-11 10:04
MOT test	number	225323762457
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/12



report date: 2024-03-28

MOT #6	2011-05-20 11:45
MOT test	number 336310641131
Result	✓ Passed
Advice (2.4.A.3)	Rear Suspension component mounting prescribed area is corroded but not considered excessive
Advice	Inner Front Tyre worn close to the legal limit (4.1.E.1)

(2.4.A.3)	
Advice Inner Front Tyre worn close to the legal limit (4	.1.E.1)
MOT #5	2010-06-19 10:42
MOT test number	203630170174
Result	✓ Passed
MOT #4	2009-06-10 16:12
MOT test number	901991969128
Result	✓ Passed
MOT #3	2008-06-18 09:34
MOT test number	664110678128
Result	✓ Passed
MOT #2	2007-06-20 12:09
MOT test number	223251377138
Result	✓ Passed
MOT #1	2006-06-21 10:34
MOT test number	442262076104

MOT #1	2006-06-21 10:34
MOT test number	443262976104
Result	✓ Passed

CarCheck.co.uk page 7/12



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

e when miscory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full research	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NE ZIG
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	1998-01-08
Last registration	2021-05-26
Complete history	See info



Registration #1	1998-01-08	19 mi
Registration #2	2006-06-21	42.634 mi
Registration #3	2007-06-20	43.767 mi
Registration #4	2008-06-18	46.663 mi
Registration #5	2009-06-10	47.920 mi
Registration #6	2010-06-19	51.545 mi
Registration #7	2011-05-20	54.443 mi
Registration #8	2012-06-11	61.049 mi
Registration #9	2013-06-13	65.819 mi
Registration #10	2013-06-14	65.820 mi
Registration #11	2014-06-27	69.362 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		71.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	3S9352952

CarCheck.co.uk page 12/12