



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D S V50
Colour	Black
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-05-23
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2021-12-29
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	28
Total items failed	5

MOT #14 2020-12-30 15:19

MOT test number 222110600613

Result ✓ Passed

Next expiry date 2021-12-29

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt

MOT #13 2020-12-30 15:19

MOT test number 848333935327

Result ✗ Failed

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Pass with rectification** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #12** 2019-09-11 09:50**MOT test number** 441032773766**Result** ✓ Passed

Minor Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect damp (5.3.2 (b))

Advice Nearside Rear tyre worn on inner edge

MOT #11 2018-10-17 08:45**MOT test number** 600799889848**Result** ✓ Passed**MOT #10** 2018-10-16 11:38**MOT test number** 174749447537**Result** ✗ Failed

MAJOR Nearside Front Position lamp not working (4.2.1 (a))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened and offside front (1.1.14 (a) (ii))

MAJOR Nearside Front Service brake excessively fluctuating and offside front (1.2.1 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9 2017-09-27 14:12**MOT test number** 387449722015**Result** ✓ Passed

Advice Offside rear tyre worn on inner edge

**MOT #8** 2016-11-14 12:30**MOT test number** 439384336296**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #7** 2015-11-10 09:57**MOT test number** 279187652254**Result** ✓ Passed**MOT #6** 2014-11-25 11:09**MOT test number** 499219224415**Result** ✓ Passed**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-11-25 16:34**MOT test number** 489679023439**Result** ✓ Passed**Notice** Oil leak**MOT #4** 2012-11-06 15:15**MOT test number** 466371612400**Result** ✓ Passed

**MOT #3** 2012-11-02 10:45**MOT test number** 985087702389**Result** ✗ Failed**Fail** Offside Front coil spring fractured (2.4.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**MOT #2** 2011-11-07 14:13**MOT test number** 856791311313**Result** ✓ Passed**MOT #1** 2011-11-07 14:13**MOT test number** 587861711334**Result** ✗ Failed**Pass with rectification** Offside Rear Rear position lamp(s) not working (1.1.A.3b)



Tax & MOT check

X

Untaxed

Tax expired:
30 June 2021

X

MOT

Expired:
29 December 2021

Tax status	Expired at 30 June 2021
Days left	1035 days too late
MOT expiry date	29 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-11-28
Last registration	2020-12-30
Complete history	See info



Registration #1	2008-11-28	9 mi
Registration #2	2011-11-07	46.535 mi
Registration #3	2012-11-02	56.508 mi
Registration #4	2012-11-06	56.508 mi
Registration #5	2013-11-25	71.201 mi
Registration #6	2014-11-25	87.475 mi
Registration #7	2015-11-10	103.970 mi
Registration #8	2016-11-14	121.784 mi
Registration #9	2017-11-14	138.598 mi
Registration #10	2018-11-14	155.412 mi
Registration #11	2019-11-14	172.226 mi
Registration #12	2020-11-14	189.040 mi
Registration #13	2021-11-14	205.854 mi
Registration #14	2022-11-14	222.668 mi
Registration #15	2023-11-14	239.482 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1436 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	421497