



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	C C200 K SE
Colour	Silver
Year of manufacture	2003
Top speed	145 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-02
Pictures	7
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-04-30
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	47
Total items failed	1

MOT #22 2023-04-27 09:23

MOT test number 757896401676

Result ✓ Passed

Next expiry date 2024-04-30

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear unable to complete full inspection of rear metal brake pipes and fuel pipes due to floor covers fitted
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21 2022-04-26 15:55

MOT test number 421582339821

Result ✓ Passed

- Advice** Unable to complete full inspection of rear brake pipes and fuel pipes due to floor covers fitted
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #20**

2022-04-26 09:17

**MOT test number**

738545932776

**Result****✗ Failed**

- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn front arm (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Unable to complete full inspection of rear brake pipes and fuel pipes due to floor covers fitted
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn front arm (5.3.4 (a) (i))
- MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19**

2021-05-01 08:00

**MOT test number**

887238781446

**Result****✓ Passed****MOT #18**

2021-04-28 14:11

**MOT test number**

230264142745

**Result****✗ Failed**

- MAJOR** Rear Exhaust system insecure (6.1.2 (a))
- MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Indicator switch faulty (4.4.2 (a) (i))

**MOT #17**

2020-08-13 11:17

**MOT test number**

147624752846

**Result**

✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to brake hose (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to brake hose (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2020-08-13 08:19

**MOT test number**

471973759020

**Result**

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Obligatory mirror missing (3.3 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to brake hose (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to brake hose (1.1.11 (c))
- MAJOR** Offside Front Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))

**MOT #15** 2019-08-05 10:40**MOT test number** 167424533551**Result** ✓ Passed**MOT #14** 2018-08-11 09:07**MOT test number** 441125266331**Result** ✓ Passed**Minor** Offside Obligatory mirror slightly damaged deteriorated (3.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Central Exhaust mounting defective bracket missing from pipe (6.1.2 (a))**MOT #13** 2017-08-19 11:35**MOT test number** 450727017685**Result** ✓ Passed**MOT #12** 2016-08-04 10:13**MOT test number** 276214603577**Result** ✓ Passed**MOT #11** 2015-08-03 15:46**MOT test number** 468745415271**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**MOT #10** 2014-08-02 14:43**MOT test number** 997204214255**Result** ✓ Passed

**MOT #9** 2013-08-19 17:26**MOT test number** 487301633225**Result** ✓ Passed**MOT #8** 2013-08-17 10:41**MOT test number** 659249323218**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Notice** Engine fan noisy**MOT #7** 2012-08-04 10:01**MOT test number** 666067912261**Result** ✓ Passed**MOT #6** 2011-08-08 08:54**MOT test number** 387310121204**Result** ✓ Passed**MOT #5** 2010-08-09 10:30**MOT test number** 861651820241**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-08-10 09:24**MOT test number** 360942329248**Result** ✓ Passed**Notice** Under body covers fitted unable to fully check brake and fuel lines**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)



MOT #3	2008-08-23 08:46
MOT test number	393986438290
Result	✓ Passed
MOT #2	2007-08-18 08:32
MOT test number	520360037255
Result	✓ Passed
MOT #1	2006-08-22 14:46
MOT test number	282934736291
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
30 April 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	3
<b>MOT expiry date</b>	30 April 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>RX53LBU</b>
Plate since	2019-06-29
Current registration	 <b>RX53LBU</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-09-01
Last registration	2023-04-27
Complete history	<a href="#">See info</a>



Registration #1	2003-09-01	7 mi
Registration #2	2006-08-22	10.319 mi
Registration #3	2007-08-18	11.178 mi
Registration #4	2008-08-23	11.850 mi
Registration #5	2009-08-10	13.844 mi
Registration #6	2010-08-09	17.367 mi
Registration #7	2011-08-08	20.343 mi
Registration #8	2012-08-04	24.809 mi
Registration #9	2013-08-17	30.712 mi
Registration #10	2013-08-19	30.712 mi
Registration #11	2014-08-02	36.104 mi
Registration #12	2015-08-03	40.514 mi
Registration #13	2016-08-03	45.924 mi
Registration #14	2017-08-03	51.334 mi
Registration #15	2018-08-03	56.744 mi
Registration #16	2019-08-03	62.154 mi
Registration #17	2020-08-03	67.564 mi
Registration #18	2021-08-03	72.974 mi
Registration #19	2022-08-03	78.384 mi
Registration #20	2023-04-27	83.794 mi
Registration #21	2023-04-27	83.794 mi
Registration #22	2023-04-27	83.794 mi
Registration #23	2023-04-27	83.794 mi
Registration #24	2023-04-27	83.794 mi

More info >



Dimensions & weight

Width	1957 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	1390 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	27194030126555