



RENAULT

LR090XG

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI 115 SWB P/V
Colour	White
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-04-03
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	36
Total items failed	18

MOT #17	2024-03-21 12:47
MOT test number	597576581186
Result	✓ Passed
Next expiry date	2025-04-03
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2024-03-13 00:02
MOT test number	963851455040
Result	✗ Failed
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2023-03-29 15:55

MOT test number

407640448205

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material 2x main front to rear (1.1.11 (c))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #14**

2023-03-29 10:02

MOT test number

872496610038

Result

✗ Failed

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material 2x main front to rear (1.1.11 (c))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt and slight play (5.3.4 (b) (ii))

MOT #13

2022-04-04 14:16

MOT test number

759841764036

Result

✓ Passed

MOT #12

2021-03-03 12:25

MOT test number

725011579388

Result

✓ Passed

**MOT #11** 2021-03-02 14:24**MOT test number** 960031553655**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view x3 (3.2 (a) (i))**MOT #10** 2020-03-26 10:44**MOT test number** 758227618802**Result** ✓ Passed**MOT #9** 2019-03-29 15:10**MOT test number** 852273369184**Result** ✓ Passed**MOT #8** 2018-03-28 15:40**MOT test number** 928702972244**Result** ✓ Passed**MOT #7** 2017-03-27 15:23**MOT test number** 174470039472**Result** ✓ Passed

**MOT #6** 2016-03-29 16:07**MOT test number** 455833449931**Result** ✓ Passed**MOT #5** 2015-03-25 16:34**MOT test number** 135614785493**Result** ✓ Passed**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #4** 2014-03-27 16:14**MOT test number** 387756484079**Result** ✓ Passed**MOT #3** 2013-03-27 16:00**MOT test number** 949006183062**Result** ✓ Passed**MOT #2** 2012-04-03 11:27**MOT test number** 115724992462**Result** ✓ Passed**Notice** Oil leak**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Play in steering rack inner joint(s)



MOT #12012-04-01 12:24

MOT test number478202592036

Result

Failed

- Notice

Oil leak
- Fail

Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
- Fail

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Nearside front tyre deteriorated
- Fail

Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice

Play in steering rack inner joint(s)



Tax & MOT check

✗
Untaxed

Tax expired:
7 March 2024

✓
MOT

Expires:
3 April 2025

Tax status	Expired at 7 March 2024
Days left	53 days too late
MOT expiry date	3 April 2025
Full MOT history	See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-31
Last registration	2024-03-21
Complete history	See info



Registration #1	2009-03-31	7 mi
Registration #2	2012-04-01	44.451 mi
Registration #3	2012-04-03	44.569 mi
Registration #4	2013-03-27	57.323 mi
Registration #5	2014-03-27	66.227 mi
Registration #6	2015-03-25	76.209 mi
Registration #7	2016-03-29	88.532 mi
Registration #8	2017-03-27	99.733 mi
Registration #9	2018-03-28	106.957 mi
Registration #10	2019-03-29	113.277 mi
Registration #11	2020-03-29	119.597 mi
Registration #12	2021-03-29	125.917 mi
Registration #13	2022-03-29	132.237 mi
Registration #14	2023-03-29	138.557 mi
Registration #15	2024-03-29	144.877 mi
Registration #16	2025-03-29	151.197 mi
Registration #17	2026-03-29	157.517 mi
Registration #18	2027-03-29	163.837 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1944 mm
Length	4782 mm
Wheel base	3098 mm
Kerb weight	1716 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	C090352