



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S
Colour	Silver
Year of manufacture	2007
Top speed	116 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	35.8 mpg
CO2 emission	189 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-05-24
Pictures	43
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-05
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	29
Total items failed	20

MOT #20	2024-01-04 14:05
MOT test number	214914232547
Result	✓ Passed
Next expiry date	2025-01-05
Advice	Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))

MOT #19	2024-01-04 14:05
MOT test number	338792733852
Result	✗ Failed
Pass with rectification	Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Advice	Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))

**MOT #18**

2023-01-06 12:41

MOT test number

990745696212

Result

✓ Passed

- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17

2021-12-16 16:40

MOT test number

795854429951

Result

✓ Passed

MOT #16

2021-01-05 13:39

MOT test number

122502267393

Result

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Play in steering rack inner joint(s) both

MOT #15

2020-01-21 10:05

MOT test number

405408889879

Result

✓ Passed

- Advice** Nearside Front Inner Play in steering rack inner joint(s)
- Advice** Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))

**MOT #14**

2019-01-22 12:28

MOT test number

578075758006

Result

✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear exhaust supporting bracket broken away from the exhaust
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear position lamp inoperative

MOT #13

2018-01-22 15:14

MOT test number

423159445722

Result

✓ Passed

MOT #12

2018-01-22 10:46

MOT test number

667722155199

Result

✗ Failed

- Fail** Front registration plate insecure (6.3.1b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #11

2017-01-27 13:22

MOT test number

701046157535

Result

✓ Passed

**MOT #10**

2017-01-21 12:29

MOT test number

139875526930

Result**✗ Failed**

- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Statutory seat belt missing (5.1.1)
- Advice** Offside Rear baby carrier not secured in place
- Fail** Nearside Rear Wheel bolt(s) missing (4.2.A.1e)
- Fail** Offside Front engine mounting deteriorated resulting in excessive movement (6.1.D.1a)
- Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Rear child seat not secured in place
- Fail** Offside Rear Statutory seat belt missing (5.1.1)
- Fail** Central Exhaust system not adequately supported exhaust bracket broken (7.1.1)

MOT #9

2016-01-12 11:22

MOT test number

356500671636

Result**✓ Passed****MOT #8**

2015-01-22 18:03

MOT test number

957972025073

Result**✓ Passed**

- Advice** Rear engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

MOT #7

2014-01-22 16:11

MOT test number

789922024045

Result**✓ Passed**

- Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #6** 2014-01-22 16:11**MOT test number** 827932924035**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Pass with rectification** Front registration plate character(s) incorrectly spaced (6.3.4a)**MOT #5** 2013-01-23 14:34**MOT test number** 108783923029**Result** ✓ Passed**MOT #4** 2012-01-23 08:48**MOT test number** 246783522072**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-01-18 14:41**MOT test number** 117398711064**Result** ✓ Passed**MOT #2** 2010-01-19 16:21**MOT test number** 691659710095**Result** ✓ Passed**Advice** Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #1	2010-01-19 13:22
MOT test number	601629210049
Result	✗ Failed
Fail	Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Notice	Child seat fitted not allowing full inspection of adult belt
Fail	Rear registration plate character(s) incorrectly spaced (6.3.4a)
Fail	Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)
Fail	Front registration plate character(s) incorrectly spaced (6.3.4a)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
5 January 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	5 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	LM56CSZ
Plate since	2019-03-28
Current registration	LM56CSZ
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-01-23
Last registration	2024-01-04
Complete history	See info



Registration #1	2007-01-23	27 mi
Registration #2	2010-01-19	11.300 mi
Registration #3	2010-01-19	11.300 mi
Registration #4	2011-01-18	14.352 mi
Registration #5	2012-01-23	16.448 mi
Registration #6	2013-01-23	18.469 mi
Registration #7	2014-01-22	21.445 mi
Registration #8	2015-01-22	23.459 mi
Registration #9	2016-01-12	25.195 mi
Registration #10	2017-01-21	30.819 mi
Registration #11	2017-01-27	30.962 mi
Registration #12	2018-01-27	31.377 mi
Registration #13	2018-01-27	31.377 mi
Registration #14	2018-01-27	31.377 mi
Registration #15	2018-01-27	31.377 mi
Registration #16	2018-01-27	31.377 mi
Registration #17	2018-01-27	31.377 mi
Registration #18	2018-01-27	31.377 mi
Registration #19	2018-01-27	31.377 mi
Registration #20	2018-01-27	31.377 mi
Registration #21	2018-01-27	31.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1306 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FX6Q3172412