





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|--------------------|
| Model | IX20 SE BLUE DRIVE |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 104 mph |
| 0 - 60 mph | 12.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 137 Nm at 5.000 rpm |
| Engine capacity | 1.396 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 130 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/10



CF18FTJ

report date: 2024-03-28

Internet history

Entry 1

Date 2021-11-20

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



CF18FTJ

report date: 2024-03-28

| NAC | \Т | بہا: حا | L |
|-----|----|---------|------|
| MC | ノレ | nis | tory |

| MOT expiry date | 2024-07-30 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 2 |
| Total items failed | 1 |

| MOT #4 | | 2023-07-17 11:38 |
|-----------|--|------------------|
| MOT test | number | 200343676443 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-07-30 |
| Advice | Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Offside Front Lower Brake disc worn, but not excessively (1.1.14 (a) (i)) | |

| MOT #3 | 2022-07-21 12:14 |
|-----------------|------------------|
| MOT test number | 553388932130 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2021-07-27 13:37 |
| MOT test number | 787231988867 |
| Result | ✓ Passed |
| | |

| MOT #1 | 2021-07-27 13:37 |
|-------------------------|---|
| MOT test number | 447260086744 |
| Result | ▼ Failed |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 248 |
| MOT expiry date | 30 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



| Owner | historv |
|-------|---|
| OWNER | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |

| Owner mistory | |
|---|-------------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
| ******** | |
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | NIE UK |
| Plate since | 100-0-0 |
| Current registration | ZIS UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 7/10



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2018-07-31 |
| Last registration | 2023-07-17 |
| Complete history | See info |



| Registration #1 | 2018-07-31 | 17 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-07-27 | 11.722 mi |
| Registration #3 | 2021-07-27 | 11.722 mi |
| Registration #4 | | 11.777 ea |
| Registration #5 | | 0.77 es |
| Registration #6 | | 11.777 au |

More info >

CarCheck.co.uk page 9/10



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 85% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| Width | 1765 mm |
|---------------------|---------|
| Height | 1600 mm |
| Length | 4120 mm |
| Wheel base | 2615 mm |
| Kerb weight | 1267 kg |
| Max. allowed weight | 1710 kg |

Additional information

| Fuel tank capacity | 50 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 10/10 |

Number of axles 2

Engine number G4FAJZ659098