



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	MATRIX GSI
Colour	Black
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	14.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	101 BHP
Max. torque	141 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	21.9 mpg
Consumption extra urban	31.0 mpg
Consumption combined	26.9 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-12-31
Pictures	23
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-10-25
Pictures	26
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #22</b>	2021-10-18 09:31
<b>MOT test number</b>	596854151819
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-10-19

<b>MOT #21</b>	2020-10-17 10:58
<b>MOT test number</b>	272789085154
<b>Result</b>	✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** N/S/R wheel damaged

<b>MOT #20</b>	2020-10-15 10:53
<b>MOT test number</b>	313317136978
<b>Result</b>	✗ Failed

- Advice** N/S/R wheel damaged
- Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Offside Rear Suspension component mounting prescribed area excessively damaged significantly reducing structural strength (5.3.6 (a) (i))

**MOT #19**

2019-10-10 15:19

**MOT test number**

681672994929

**Result**

✓ Passed

**Advice** Bumper damaged off side rear.**Advice** Offside Rear wheel rim damaged.**MOT #18**

2019-10-10 10:37

**MOT test number**

936048040389

**Result**

✗ Failed

**Fail** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Bumper damaged off side rear.**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear wheel rim damaged.**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #17**

2018-10-20 10:55

**MOT test number**

719450396060

**Result**

✓ Passed

**Advice** Offside Rear bumper Insecure**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2018-10-19 15:48**MOT test number** 112689302253**Result** ✗ Failed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear bumper Insecure**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15** 2017-10-19 10:59**MOT test number** 731476221740**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)**MOT #14** 2017-10-17 14:20**MOT test number** 857054983085**Result** ✗ Failed**Advice** Items removed from driver's view prior to test**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**MOT #13** 2016-10-19 13:55**MOT test number** 631203526589**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Front Suspension arm has slight play in a pin/bush both (2.4.G.2)**Advice** Rear brake fluctuating, but not excessively both (3.7.B.3)**MOT #12** 2016-10-17 11:04**MOT test number** 771979930929**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Front Suspension arm has slight play in a pin/bush both (2.4.G.2)**Fail** Rear Anti-roll bar has excessive play in a pin/bush both D bushes (2.4.G.2)**Advice** Rear brake fluctuating, but not excessively both (3.7.B.3)**Pass with rectification** Nearside Headlamp aim too low (1.8)



MOT #11 2015-10-20 14:32

MOT test number 226327226194

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Suspension arm has slight play in a pin/bush both (2.4.G.2)
- Advice** Child seat fitted not allowing full inspection of a seat belt
- Advice** Rear brake fluctuating, but not excessively both (3.7.B.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt both (2.5.C.1a)
- Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)

MOT #10 2015-10-20 14:32

MOT test number 321150217480

Result ✗ Failed

- Advice** Rear brake fluctuating, but not excessively both (3.7.B.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt both (2.5.C.1a)
- Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)
- Advice** Child seat fitted not allowing full inspection of a seat belt
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Suspension arm has slight play in a pin/bush both (2.4.G.2)
- Pass with rectification** Offside Headlamp aim too low (1.8)

**MOT #9** 2014-09-29 16:36**MOT test number** 848932874205**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #8** 2013-09-30 14:21**MOT test number** 407163373273**Result** ✓ Passed**MOT #7** 2013-09-27 15:35**MOT test number** 229060073276**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2012-09-21 12:36**MOT test number** 397155762425**Result** ✓ Passed**Notice** Air bag light on

**MOT #5** 2011-09-28 17:44**MOT test number** 868741871264**Result** ✓ Passed**MOT #4** 2011-09-28 17:44**MOT test number** 859941871266**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2010-12-01 12:08**MOT test number** 430705030479**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-12-01 09:25**MOT test number** 211255230319**Result** ✗ Failed**Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-12-02 15:27**MOT test number** 103676339325**Result** ✓ Passed**Notice** Front brake discs worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-12-21
Last registration	2021-10-18
Complete history	<a href="#">See info</a>



Registration #1	2006-12-21	25 mi
Registration #2	2009-12-02	30.968 mi
Registration #3	2010-12-01	38.988 mi
Registration #4	2010-12-01	38.988 mi
Registration #5	2011-09-28	42.288 mi
Registration #6	2012-09-21	47.718 mi
Registration #7	2013-09-27	54.592 mi
Registration #8	2013-09-30	54.648 mi
Registration #9	2014-09-29	62.280 mi
Registration #10	2015-10-20	70.394 mi
Registration #11	2015-10-20	70.394 mi
Registration #12	2016-10-17	77.843 mi
Registration #13	2016-10-17	77.843 mi
Registration #14	2016-10-17	77.843 mi
Registration #15	2016-10-17	77.843 mi
Registration #16	2016-10-17	77.843 mi
Registration #17	2016-10-17	77.843 mi
Registration #18	2016-10-17	77.843 mi
Registration #19	2016-10-17	77.843 mi
Registration #20	2016-10-17	77.843 mi
Registration #21	2016-10-17	77.843 mi
Registration #22	2016-10-17	77.843 mi
Registration #23	2016-10-17	77.843 mi
Registration #24	2016-10-17	77.843 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1635 mm
Length	4025 mm
Wheel base	2600 mm
Kerb weight	1349 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	G4ED5286490