




report date: 2024-03-28

General information

Make	VOLVO
Model	S80 T SE SPORT
Colour	Silver
Year of manufacture	2007
Top speed	143 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	28.5 mpg
CO2 emission	244 g/km
CO2 label	L





## Internet history

### Entry 3

Date	2023-08-19
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2


Date	2022-09-29
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date	2022-07-26
Pictures	34
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2024-10-01
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #16	2023-10-02 13:37
MOT test number	665345383225
Result	✓ Passed
Next expiry date	2024-10-01

MOT #15	2023-10-02 10:18
MOT test number	639565602446
Result	✗ Failed
Advice	Offside Rear Nail in tyre
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #14	2022-09-28 16:13
MOT test number	188759262806
Result	✓ Passed

MOT #13	2021-12-08 17:18
MOT test number	703725882590
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2020-11-30 13:28**MOT test number** 492531065135**Result** ✓ Passed**Advice** Rear Suspension component pin or bush slightly worn both trailing arms (5.3.4 (a) (i))**MOT #11** 2019-11-28 17:11**MOT test number** 418466280061**Result** ✓ Passed**MOT #10** 2018-11-29 14:42**MOT test number** 442658747287**Result** ✓ Passed**Advice** Rear tyres slightly distorted**MOT #9** 2017-12-14 16:22**MOT test number** 868827867158**Result** ✓ Passed**MOT #8** 2017-01-11 16:46**MOT test number** 373154718733**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Tyre worn close to the legal limit both and distorted (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-01-07 17:19**MOT test number** 472278999829**Result** ✓ Passed

**MOT #6** 2015-01-19 15:22**MOT test number** 659019515098**Result** ✓ Passed**Advice** Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres distorted**MOT #5** 2014-01-15 14:06**MOT test number** 505405714067**Result** ✓ Passed**Advice** Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-01-10 15:38**MOT test number** 818930813069**Result** ✓ Passed**Notice** Both rear tyres perished**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-01-19 09:56**MOT test number** 609599812061**Result** ✓ Passed**Notice** Rear tyres slightly distorted**MOT #2** 2011-01-05 12:02**MOT test number** 348005901013**Result** ✓ Passed



MOT #1	2010-01-13 12:15
MOT test number	170783010081
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
1 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	1 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-01-18
Last registration	2023-10-02
Complete history	<a href="#">See info</a>



Registration #1	2007-01-18	24 mi
Registration #2	2010-01-13	16.373 mi
Registration #3	2011-01-05	20.719 mi
Registration #4	2012-01-19	26.150 mi
Registration #5	2013-01-10	38.967 mi
Registration #6	2014-01-15	39.578 mi
Registration #7	2015-01-19	45.525 mi
Registration #8	2016-01-07	49.259 mi
Registration #9	2017-01-11	53.029 mi
Registration #10	2017-12-14	55.651 mi
Registration #11	2018-01-01	55.651 mi
Registration #12	2018-01-01	55.651 mi
Registration #13	2018-01-01	55.651 mi
Registration #14	2018-01-01	55.651 mi
Registration #15	2018-01-01	55.651 mi
Registration #16	2018-01-01	55.651 mi
Registration #17	2018-01-01	55.651 mi
Registration #18	2018-01-01	55.651 mi
Registration #19	2018-01-01	55.651 mi
Registration #20	2018-01-01	55.651 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1490 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1553 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4095522