



SXI6KZN

report date: 2024-03-29

General information

Make	MAZDA
Model	cx-3 SE-L NAV
Colour	Red
Year of manufacture	2016
Top speed	119 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	204 Nm at 2.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 2

Date	2023-06-05
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-06-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-16
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	13
Total items failed	4

MOT #7	2023-07-17 13:37
MOT test number	692405437840
Result	✓ Passed
Next expiry date	2024-07-16

MOT #6	2023-02-28 12:07
MOT test number	644781050056
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #5	2022-03-03 17:02
MOT test number	371133985668
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))

**MOT #4**

2022-02-25 12:19

MOT test number

829490872342

Result

✗ Failed

Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Brake pipe excessively corroded Pipe to o/s/f flexi (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Brake pipe excessively corroded Pipe to n/s/f flexi (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))**MOT #3**

2021-02-05 12:44

MOT test number

696678772510

Result

✓ Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened FACE (1.1.14 (a) (iii))**MOT #2**

2020-02-06 11:03

MOT test number

523399893535

Result

✓ Passed

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))**Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))**Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #1	2019-02-15 15:35
MOT test number	479617024978
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
16 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	16 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	SX16KZN
Plate since	2019-09-29
Current registration	SX16KZN
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-03-03
Last registration	2023-07-17
Complete history	See info



Registration #1	2016-03-03	22 mi
Registration #2	2019-02-15	19.067 mi
Registration #3	2020-02-06	23.290 mi
Registration #4	2021-02-05	27.575 mi
Registration #5	2022-02-05	29.277 mi
Registration #6	2022-02-05	29.277 mi
Registration #7	2022-02-05	29.277 mi
Registration #8	2022-02-05	29.277 mi
Registration #9	2022-02-05	29.277 mi
Registration #10	2023-07-17	29.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	85%
Children	79%
Pedestrian	84%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1535 mm
Length	4275 mm
Wheel base	2570 mm
Kerb weight	1155 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	PE 30840792