





### General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Blue
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E







# Internet history

Entry	1
Date	

Pictures

2022-03-04

12


Listing price

View report









source: cargurus.co.uk



## MOT history

MOT expiry date	2022-08-12
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	21
Total items failed	3

MOT #15	2021-07-17 12:00	
MOT test number	672210163648	
Result	✓ Passed	
Next expiry date	2022-08-12	
<b>Minor</b> Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated split at small clip (6.1.7 (g) (i))		

MOT #14	2020-08-13 10:02
MOT test number	471424106212
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated cv boot split around small clip (6.1.7 (g) (i))	

MOT #13	2019-05-14 12:25
MOT test number	601743796919
Result	✓ Passed
Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	

MOT #12	2018-05-11 13:56
MOT test number	774049371332
Result	✓ Passed





MOT #11	2018-05-10 10:51
MOT test number	396626165934
Result	🗙 Failed
Fail Nearside front brake binding (3.7.B.1)	
MOT #10	2017-05-12 10:51
MOT test number	112956895396
Result	✓ Passed
MOT #9	2016-07-09 11:46
MOT test number	178759552429
Result	✓ Passed
MOT #8	2016-07-02 10:30
MOT test number	262920069017
Result	🗙 Failed
Fail Nearside Front Lower Front suspension has excessive movement at a way	vishbone pin or bush (2.5.A.1c)
MOT #7	2015-07-15 10:05
MOT test number	406136595142
Result	✓ Passed
MOT #6	2014-09-17 10:58
MOT test number	735670164270
Result	✓ Passed
MOT #5	2013-09-16 10:43
MOT test number	515599853231
Result	✓ Passed
Notice Both rear tyres age cracking	



MOT #4		2012-09-18 10:00
MOT test	number	346082462427
Result		✓ Passed
Notice	Items removed from driver's view prior to test	
Notice	Under-trays fitted obscuring some underside components	
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)		
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	N/S rear child seat	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #3		2012-09-13 12:04
MOT test	number	539207052289
Result		🗙 Failed
Notice	N/S rear child seat	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Wiper blades fittings incorrect.	
Advice movemen	Nearside Front Lower Suspension arm rubber bush deteriorated but not ret (2.4.G.2)	esulting in excessive
Notice	Items removed from driver's view prior to test	
Notice	Under-trays fitted obscuring some underside components	
<b>Fail</b> N	earside Front Tyre not fitted in accordance with side wall instructions (4.1.D	D.1f)
Notice	Child seat fitted not allowing full inspection of adult belt	

**PK57HEV** 

report date: 2024-03-29





MOT #2		2011-09-13 15:26
MOT test	number	695836451261
Result		Passed
Notice	Front tyres worn on edge	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	O/E trims & covers fitted	
MOT #1		2010-09-03 11:56
MOT test	number	594316740256
Result		✓ Passed



PK57HEV report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 29 July 2022	<b>X</b> <b>MOT</b> Expired: 12 August 2022
Tax status	Expired at 29 July 2022
Days left	641 days too late
MOT expiry date	12 August 2022
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETO
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CUT-S
Date	*
Category	AMPT
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
and the second sec	
***********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-09-14
Last registration	2021-07-17
Complete history	See info



Registration #1	2007-09-14	6 mi
Registration #2	2010-09-03	12.054 mi
Registration #3	2011-09-13	15.692 mi
Registration #4	2012-09-13	20.377 mi
Registration #5	2012-09-18	20.489 mi
Registration #6	2013-09-16	24.204 mi
Registration #7	2014-09-17	28.470 mi
Registration #8	2015-07-15	31.147 mi
Registration #9	2016-07-02	38.938 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

**NCAP** rating

Video

see crash video

\*\*\*\*



#### Dimensions & weight Width 1660 mm Height 1544 mm Length 3828 mm Wheel base 2465 mm Kerb weight 1069 kg Max. allowed weight 1480 kg Additional information Fuel tank capacity 50 I **Fuel delivery Multi-Point Injection** Number of doors 3

CarCheck.co.uk

Number of seats	4
Number of axles	2
Engine number	BMD 375475