



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX20 ACTIVE
Colour	Grey
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 3

Date	2022-11-14
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 2


Date	2022-11-13
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-18
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-14
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	15
Total items failed	3

MOT #14	2023-11-15 13:29
MOT test number	800760456255
Result	✓ Passed
Next expiry date	2024-11-14
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Rear Sub-frame is corroded but structural rigidity is not significantly reduced [axle beam] (6.1.1 (c) (i))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #13	2022-11-14 14:47
MOT test number	918934317319
Result	✓ Passed

MOT #12	2022-11-14 14:47
MOT test number	145464338802
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low adjust (4.1.2 (a))
Pass with rectification	Nearside Headlamp aim projected beam image is obviously incorrect bulb fitted incorrectly (4.1.2 (c))

**MOT #11** 2022-05-24 12:58**MOT test number** 371397403715**Result** ✓ Passed**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #10** 2021-06-21 12:32**MOT test number** 333587388404**Result** ✓ Passed**MOT #9** 2021-02-15 11:55**MOT test number** 976576061429**Result** ✓ Passed**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2020-02-04 11:20**MOT test number** 278721602188**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2019-02-15 10:13**MOT test number** 811221666386**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Side repeater slightly discoloured (4.4.3 (a))**MOT #6** 2018-02-06 14:14**MOT test number** 189267740554**Result** ✓ Passed**MOT #5** 2017-02-23 15:36**MOT test number** 826363840497**Result** ✓ Passed**MOT #4** 2016-02-09 11:14**MOT test number** 294435917648**Result** ✓ Passed**MOT #3** 2016-02-09 11:14**MOT test number** 768006127542**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2015-02-20 14:41**MOT test number** 478931955061**Result** ✓ Passed



MOT #1	2014-03-19 12:14
MOT test number	688018974090
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
14 November 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	14 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-04-15
Last registration	2023-11-15
Complete history	See info



Registration #1	2011-04-15	22 mi
Registration #2	2014-03-19	16.661 mi
Registration #3	2015-02-20	21.299 mi
Registration #4	2016-02-09	25.693 mi
Registration #5	2016-02-09	25.693 mi
Registration #6	2017-02-23	29.782 mi
Registration #7	2018-02-06	33.937 mi
Registration #8	2019-02-15	37.861 mi
Registration #9	2020-02-04	42.084 mi
Registration #10	2020-02-04	42.084 mi
Registration #11	2020-02-04	42.084 mi
Registration #12	2020-02-04	42.084 mi
Registration #13	2020-02-04	42.084 mi
Registration #14	2020-02-04	42.084 mi
Registration #15	2020-02-04	42.084 mi
Registration #16	2020-02-04	42.084 mi
Registration #17	2020-02-04	42.084 mi
Registration #18	2020-02-04	42.084 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FABZ370121