





report date: 2024-03-28

### General information

| Make                | BMW               |
|---------------------|-------------------|
| Model               | 330 730LD M SPORT |
| Colour              | Grey              |
| Year of manufacture | 2019              |
| Top speed           | 155 mph           |
| Gearbox             | 8 speed automatic |

# Engine & fuel consumption

| Power                | 261 BHP             |
|----------------------|---------------------|
| Max. torque          | 620 Nm at 2.000 rpm |
| Engine capacity      | 2.993 сс            |
| Cylinders            | 6                   |
| Fuel type            | Diesel              |
| Consumption combined | 44.1 mpg            |
| CO2 emission         | 142 g/km            |
| CO2 label            | F                   |



CarCheck.co.uk page 1/10



### Internet history

#### Entry 1

Date 2021-01-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date    | 2025-01-29 |
|--------------------|------------|
| MOT pass rate      | 67 %       |
| MOT passed         | 2          |
| Failed MOT tests   | 1          |
| Total advice items | 0          |
| Total items failed | 2          |

| MOT #3           | 2024-01-26 16:01 |
|------------------|------------------|
| MOT test number  | 868774335021     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-01-29       |

| MOT #2          | 2023-01-30 16:41 |
|-----------------|------------------|
| MOT test number | 665102492212     |
| Result          | ✓ Passed         |

**MOT test number** 127271298410

**Result** X Failed

**Pass with rectification** Offside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure Sidewall (5.2.3 (d) (ii))

**Pass with rectification** Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure Sidewall (5.2.3 (d) (ii))

CarCheck.co.uk page 3/10



### Tax & MOT check



| Tax status       | Valid until 1 February |
|------------------|------------------------|
| Days left        | 279                    |
| MOT expiry date  | 29 January 2025        |
| Full MOT history | See MOT history        |

#### Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | Н          |
| First licence fee (12 months)                        | £ 255,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 645,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| ,  |           |     |
|--|-----------|-----|
| For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I   |           | ve? |
|  |           |     |
|  |           |     |
|  |           |     |
|  |           |     |
| manage and the same and the sam |           |     |
|  |           |     |
| ***************************************  |           |     |
|  | More info | >   |
| Plate changes  See in this check if this BMW had different number plates.  |           |     |
| Number of plates   |           | ,   |
| Current registration   | NK SIES   |     |
| Plate since  |           |     |
| Current registration   | NK NIE    |     |
| Plate since  |           |     |
|  | More info | >   |
|  |           |     |

CarCheck.co.uk page 7/10



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 5          |
| First mileage registration | 2019-12-17 |
| Last registration          | 2024-01-26 |
| Complete history           | See info   |



| Registration #1 | 2019-12-17 | 22 mi     |
|-----------------|------------|-----------|
| Registration #2 |            | 77,777 44 |
| Registration #3 | 2023-01-30 | 35.179 mi |
| Registration #4 |            | 11.777 es |
| Registration #5 |            | 11.777 es |

More info >

CarCheck.co.uk page 9/10



Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 60295 |                 |
| 60482 |                 |
| 0501  |                 |
| 60566 |                 |
| 60567 |                 |
| 60569 |                 |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 91%             |
| Children       | 85%             |
| Pedestrian     | 81%             |
| Safety systems | 59%             |
| Overall rating | 81%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1902 mm |
|---------------------|---------|
| Height              | 1479 mm |
| Length              | 5260 mm |
| Max. allowed weight | 2560 kg |

### Additional information

| Number of seats | 5        |
|-----------------|----------|
| Number of axles | 2        |
| Engine number   | 57525687 |

CarCheck.co.uk page 10/10