





# General information

Make	PEUGEOT
Model	PARTNER BLUE HDI PROFESSIONAL L1
Colour	White
Year of manufacture	2018
Top speed	101 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С





## Internet history

Entry	2
Date	

Pictures

2021-12-23

14

Listing price

View report



source: autotrader.co.uk

## Entry 1

Date

Pictures


Listing price

2021-12-09 14


View report



source: autotrader.co.uk









# MOT history

MOT expiry date	2025-01-08
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	24
Total items failed	3

MOT #7	2023-12-22 13:04
MOT test number	887760471875
Result	✓ Passed
Next expiry date	2025-01-08
Advice Nearside Rear Tyre worn close to legal limit/worn on edge	e (5.2.3 (e))
Advice Nearside Front Tyre worn close to legal limit/worn on edg	je (5.2.3 (e))
Advice Offside Rear Tyre worn close to legal limit/worn on edge	(5.2.3 (e))

# MOT #6 2023-01-09 13:52 MOT test number 685331002859 Result ✓ Passed Advice High level brake light inoperative





MOT #5	2023-01-06 12:2	20
MOT test	number 51302499306	56
Result	× Faile	ed
<b>MAJOR</b> (b) (ii))	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4	
Advice	High level brake light inoperative	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))	
<b>MAJOR</b> (5.3.4 (b) (	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (ii))	
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	

MOT #4	2021-12-08 09:35
MOT test number	938780157129
Result	✓ Passed
Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice Central Rear Upper Stop light not working.	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i	i))



wb67FyN report date: 2024-03-28

МОТ #3	2021-12-08 09:35	
MOT test number	276495364244	
Result	🗙 Failed	
Advice Central Rear Upper Stop light not working.		
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
Pass with rectificationOffside Front Position lamp not working (4.2.1 (a) (ii))		
Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))		

MOT #2	202	21-01-13 15:40
MOT test	<b>number</b> 9	944607058623
Result		🗸 Passed
Advice	Front Brake disc worn, but not excessively Close To Wear Markers (1.1.14 (a) (i))	
Minor	Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i	))

MOT #1	2	2021-01-13 15:40
MOT test number		975949890372
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	
Advice Front Brake disc worn, but not excessively Close To Wear Markers (1.1.14 (a) (i))		
Minor Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))		



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 8 January 2025
Tax status	Valid until 1 December
Days left	217
MOT expiry date	8 January 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-





## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





## Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





## Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-01-26
Last registration	2023-12-22
Complete history	See info



Registration #1	2018-01-26	7 mi
Registration #2	2021-01-13	29.739 mi
Registration #3	2021-01-13	29.739 mi
Registration #4	2021-12-08	34.098 mi
Registration #5	2021-12-08	34.098 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 est
Registration #8 Registration #9		11.577 es

More info >





## Car features

S0225	Air conditionin
\$0295	
50482	
50501	
50566	
50567	
50569	

# Dimensions & weight

Number of axles

**Engine number** 

Width	1810 mm
Height	1828 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1331 kg
Max. allowed weight	2185 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	3

2

JBHB0082207