





report date: 2024-03-28

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	Silver
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-12-13

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-12-20
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #14		2023-12-19 18:01
MOT test	number	607016878418
Result		✓ Passed
Next expi	y date	2024-12-20
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #13		2023-12-19 14:19
MOT test	number	779111300128
Result		X Failed
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Ex	chaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

336370231103

Result

Minor
(b) (i))

Advice

Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))

Minor
Offside Front Anti-roll bar ball joint dust cover severely deteriorated Upper & lower (5.3.4 (b) (i))

Advice
Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #11 2022-12-21 14:38 **MOT** test number 837041721513 Result × Failed Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Pass with rectification Minor Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated Upper & lower (5.3.4 (b) (i)) **Advice** Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b)) Pass with rectification Front Position lamp not working both (4.2.1 (a) (ii)) Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated Upper & lower (5.3.4 (b) (i)) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #10	2021-12-20 18:12
MOT test number	952359728154
Result	✓ Passed

MOT #9	2020-11-06 10:46
MOT test number	743732839772
Result	✓ Passed

CarCheck.co.uk page 4/13



Result

FP590NH

report date: 2024-03-28

✓ Passed

MOT #8	2019-11-27 10:23
MOT test number	801581342404
Result	✓ Passed
MOT #7	2018-11-28 12:29
MOT test number	990149557821
Result	✓ Passed
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously w	veakened (1.1.14 (a) (ii))
MOT #6	2017-11-20 11:07
MOT test number	138061717640
Result	✓ Passed
MOT #5	2016-11-21 12:01
MOT test number	303568197408
Result	✓ Passed
MOT #4	2015-11-28 12:07
MOT test number	736277249995
Result	✓ Passed
MOT #3	2014-11-29 11:25
MOT test number	918303434342
Result	✓ Passed
MOT #2	2013-12-14 09:46
MOT test number	907788443389

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2012-12-31 13:22

MOT test number 296776262308

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

_	
Owner	hictory
OWILL	HISLOIV

,	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-12-07
Last registration	2023-12-19
Complete history	See info



Registration #1	2009-12-07	9 mi
Registration #2	2012-12-31	17.002 mi
Registration #3	2013-12-14	28.991 mi
Registration #4	2014-11-29	42.161 mi
Registration #5	2015-11-28	54.302 mi
Registration #6	2016-11-21	63.025 mi
Registration #7	2017-11-20	70.960 mi
Registration #8	2018-11-28	77.717 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.77 66
Registration #12		11.777 es
Registration #13		9.77 66
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 mg

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2

Engine number 1KR0827053