



WF6IVDC

report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER D ALL4
Colour	White
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	64.2 mpg
CO2 emission	129 g/km
CO2 label	D







Internet history

Entry 1

Date	2022-06-01
Pictures	40
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-04
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	17
Total items failed	11

MOT #13	2023-04-26 10:55
MOT test number	805937893424
Result	✓ Passed
Next expiry date	2024-05-04

MOT #12	2022-05-03 13:21
MOT test number	921029552878
Result	✓ Passed

MOT #11	2022-05-03 13:21
MOT test number	828740809482
Result	✗ Failed
Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #10	2021-05-05 10:53
MOT test number	243040028533
Result	✓ Passed
Advice Child Seat fitted not allowing full inspection of adult belt	

**MOT #9** 2021-05-05 10:53**MOT test number** 298759302355**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2020-07-23 14:55**MOT test number** 947162357695**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2020-07-22 14:15**MOT test number** 162561773749**Result** ✗ Failed**Fail** Nearside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen inop (3.5 (a))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen inop (3.5 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2019-05-08 12:27**MOT test number** 320281472807**Result** ✓ Passed

**MOT #5** 2019-05-02 09:34**MOT test number** 985499680462**Result** ✗ Failed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside rear brake disc blue**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**MOT #4** 2018-02-02 10:22**MOT test number** 511953549644**Result** ✓ Passed**MOT #3** 2017-01-06 10:40**MOT test number** 636661566823**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn on the inner and outer edges**Advice** Nearside Front Tyre worn on the inner and outer edges 205/55/17**Advice** Engine Management Light on



MOT #2	2016-01-08 14:43
MOT test number	249144937836
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2014-10-29 11:56
MOT test number	277202404398
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
4 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	WF61VDC
Plate since	2019-09-28
Current registration	WF61VDC
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-11-14
Last registration	2023-04-26
Complete history	See info



Registration #1	2011-11-14	17 mi
Registration #2	2014-10-29	29.591 mi
Registration #3	2016-01-08	41.197 mi
Registration #4	2017-01-06	52.687 mi
Registration #5	2018-02-02	65.555 mi
Registration #6	2019-05-02	81.599 mi
Registration #7	2019-05-08	81.599 mi
Registration #8	2020-07-22	84.971 mi
Registration #9	2020-09-01	85.377 mi
Registration #10	2020-10-01	85.377 mi
Registration #11	2020-11-01	85.377 mi
Registration #12	2020-12-01	85.377 mi
Registration #13	2021-01-01	85.377 mi
Registration #14	2021-02-01	85.377 mi
Registration #15	2021-03-01	85.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Kerb weight	1380 kg
Max. allowed weight	1850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	71247709