



report date: 2024-03-29

General information

| | |
|---------------------|-----------------------------|
| Make | CITROEN |
| Model | DS3 PURETECH DSTYLE ICE S/S |
| Colour | Blue |
| Year of manufacture | 2015 |
| Top speed | 118 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 109 BHP |
| Max. torque | 205 Nm at 1.500 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 104 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-06 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-12-27 |
| MOT pass rate | 70 % |
| MOT passed | 7 |
| Failed MOT tests | 3 |
| Total advice items | 12 |
| Total items failed | 4 |

| | |
|------------------|------------------|
| MOT #10 | 2022-12-28 09:51 |
| MOT test number | 157641141752 |
| Result | ✓ Passed |
| Next expiry date | 2023-12-27 |

| | |
|-------------------------|---|
| MOT #9 | 2022-12-28 09:51 |
| MOT test number | 758244575421 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Front Position lamp not working Lamp inop..... (4.2.1 (a) (ii)) |
| Pass with rectification | Front Windscreen wiper does not clear the windscreen effectively Blades split and poor wipe to screen..... (3.4 (b) (ii)) |
| Pass with rectification | Offside Front Coil spring fractured or broken Broken spring..... (5.3.1 (b) (i)) |
| Pass with rectification | Front Windscreen washer provides insufficient washer liquid (3.5 (a)) |

| | |
|-----------------|------------------|
| MOT #8 | 2022-02-10 15:59 |
| MOT test number | 540340199256 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #7 | 2021-11-03 12:52 |
| MOT test number | 221168201142 |
| Result | ✓ Passed |

**MOT #6** 2021-03-11 09:09**MOT test number** 373127612132**Result** ✓ Passed**MOT #5** 2020-03-09 17:29**MOT test number** 409272137292**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-03-09 14:08**MOT test number** 549871632645**Result** ✗ Failed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2019-03-15 09:48**MOT test number** 714848322801**Result** ✓ Passed**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))



| | |
|-----------------|--|
| MOT #2 | 2019-03-13 14:21 |
| MOT test number | 924170296002 |
| Result | ✗ Failed |
| Advice | Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| MAJOR | Oil leaking excessively from engine (8.4.1 (a) (i)) |

| | |
|-----------------|--|
| MOT #1 | 2018-03-13 11:47 |
| MOT test number | 153957194345 |
| Result | ✓ Passed |
| Advice | Items removed from driver's view prior to test |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | PK15UVM |
| Plate since | 2019-03-29 |
| Current registration | PK15UVM |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2015-04-19 |
| Last registration | 2022-12-28 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-04-19 | 16 mi |
| Registration #2 | 2018-03-13 | 23.654 mi |
| Registration #3 | 2019-03-13 | 34.165 mi |
| Registration #4 | 2019-03-15 | 34.165 mi |
| Registration #5 | 2020-03-09 | 43.504 mi |
| Registration #6 | 2020-03-09 | 43.504 mi |
| Registration #7 | 2022-12-28 | 55.277 mi |
| Registration #8 | 2022-12-28 | 55.277 mi |
| Registration #9 | 2022-12-28 | 55.277 mi |
| Registration #10 | 2022-12-28 | 55.277 mi |
| Registration #11 | 2022-12-28 | 55.277 mi |
| Registration #12 | 2022-12-28 | 55.277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 71% |
| Pedestrian | 35% |
| Safety systems | 83% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1708 mm |
| Height | 1460 mm |
| Length | 3948 mm |
| Wheel base | 2464 mm |
| Kerb weight | 1070 kg |
| Max. allowed weight | 1578 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | XV120071853 |