



General information

Make	MINI
Model	MINI (R57) COOPER SD
Colour	Orange
Year of manufacture	2011
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	С





Internet history

Entry 2	
Date	2021-11-06
Pictures	12
Listing price	<u>View report</u>



source: cargurus.co.uk

Entry 1


Date

Pictures

Listing price

2021-11-04 26

View report



source: autotrader.co.uk









MOT history

MOT expiry date	2025-03-05
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	17
Total items failed	1

MOT #12		2024-03-06 09:23
MOT test	number	355781167205
Result		✓ Passed
Next expi	ry date	2025-03-05
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Tyre pressure waning light staying on.	





MOT #11	2024-03-05 11:52
MOT test number	492047482651
Result	🗙 Failed
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Tyre pressure waning light staying on.	
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #10	2022-11-24 09:31
MOT test number	740882263882
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

МОТ #9	2021-11-05 09:48
MOT test number	759051642588
Result	✓ Passed
МОТ #8	2020-11-13 16:12
MOT test number	737655478147
Result	✓ Passed

MOT #7	2019-04-01 11:44
MOT test number	183296300802
Result	✓ Passed





MOT #6	2018-04-11 10:50
MOT test number	953066645396
Result	Passed
AdviceTyres starting to crack on side walls (all)AdviceFront Brake pad(s) wearing thin (3.5.1g)	

MOT #5	2017-04-07 08:11
MOT test number	484195126969
Result	✓ Passed

MOT #4		2017-04-07 08:11
MOT test number		322814706218
Result		🗙 Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	

MOT #3	2016-04-18 08:26
MOT test number	179387853256
Result	✓ Passed
MOT #2	2015-04-14 10:46
MOT test number	249334405154

Result	✓ Passed
MOT #1	2014-04-25 08:40
MOT test number	926585114126
Result	✓ Passed



Tax & MOT check

Tax due: 1 March 2025	✓ Taxed	Expires: 5 March 2025	мот
Tax status			Valid until 1 March
Days left			306
MOT expiry date			5 March 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-08-25
Last registration	2024-03-06
Complete history	See info



Registration #1	2011-08-25	11 mi
Registration #2	2014-04-25	20.940 mi
Registration #3	2015-04-14	27.159 mi
Registration #4	2016-04-18	31.929 mi
Registration #5	2017-04-07	40.356 mi
Registration #6	2017-04-07	40.356 mi
Registration #7	2018-04-11	48.671 mi
Registration #8	2019-04-01	57.229 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weightWidth1683 mmHeight1414 mmLength3729 mmWheel base2467 mmKerb weight1250 kgMax. allowed weight1680 kg

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

72347808