






#### General information

| 1 SERIES 116D EFFICIENTDYNAMICS |  |
|---------------------------------|--|
|                                 |  |
|                                 |  |
|                                 |  |
| ds                              |  |
| anual                           |  |
|                                 |  |

### Engine & fuel consumption

| Power                   | 114 BHP             |
|-------------------------|---------------------|
| Max. torque             | 260 Nm at 1.750 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 64.2 mpg            |
| Consumption extra urban | 83.1 mpg            |
| Consumption combined    | 74.3 mpg            |
| CO2 emission            | 99 g/km             |
| CO2 label               | А                   |





# Internet history

Entry 1

Date

Pictures

2021-01-28

8

Listing price

View report









source: autoonline.co.uk



# MOT history

| MOT expiry date    | 2024-12-21 |
|--------------------|------------|
| MOT pass rate      | 90 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 1          |
| Total advice items | 12         |
| Total items failed | 2          |

| MOT #10  | 2023-12-21 09:58     |
|--|----------------------|
| MOT test number  | 197763858185         |
| Result   | ✓ Passed             |
| Next expiry date   | 2024-12-21           |
| Advice Offside Front Tyre worn close to legal limit/worn on edge Wearing thin on the tyre. (5.2.3 (e))                         | outer portion of the |
| Advice Advise engine bay covers & under trays fitted obscuring some components   |                      |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))   |                      |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge Low & very thin on the outer portion of the tyre (5.2.3 (e)) |                      |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                      |

| МОТ #9  | 2022-12-19 12:45 |
|---|------------------|
| MOT test number   | 511368570433     |
| Result  | ✓ Passed         |
| Advice Advise engine bay covers & under trays fitted obscuring some components. |                  |

| MOT #8     |  | 2021-12-17 11:31 |
|------------|--|------------------|
| MOT test r | number   | 769424457503     |
| Result     |  | 🗸 Passed         |
| Advice     | Advise engine bay covers & under trays fitted obscuring some testable componer | its.             |





| MOT #7          | 2020-12-22 15:36 |
|-----------------|------------------|
| MOT test number | 657989309570     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #6          | 2020-05-28 08:29 |
| MOT test number | 409105304639     |
| Result          | ✓ Passed         |

Rear Brake disc worn, pitted or scored, but not seriously weakened inner edge (1.1.14 (a) (ii)) Advice

| MOT #5     |  | 2019-04-11 10:54 |
|------------|--|------------------|
| MOT test r | number   | 512353315439     |
| Result     |  | ✓ Passed         |
| Advice     | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) | )                |

| MOT #4     |  | 2018-04-05 08:02 |
|------------|--|------------------|
| MOT test i | number   | 835341298900     |
| Result     |  | ✓ Passed         |
| Advice     | Offside Rear Tyre worn close to the legal limit (4.1.E.1)  |                  |
| Advice     | Rear rear wiper  |                  |
| Advice     | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |                  |

| MOT #3          | 2017-04-24 09:45 |
|-----------------|------------------|
| MOT test number | 247751060495     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #2          | 2016-04-12 09:52 |

| MOT test number | 159974992856 |
|-----------------|--------------|
| Result          | ✓ Passed     |





| MOT #1                  |   | 2016-04-12 09:52 |
|-------------------------|---|------------------|
| MOT test number         |   | 876235774397     |
| Result                  |   | 🗙 Failed         |
| Pass with rectification | Nearside Front Headlamp aim too low (1.8) |                  |
| Pass with rectification | Offside Front Headlamp aim too low (1.8)  |                  |



Tax & MOT check

| <b>Tax due:</b><br>1 February 2025 | ✓<br>Taxed | <b>Expires:</b><br>21 December 2024 | ✓<br>МОТ               |
|------------------------------------|------------|-------------------------------------|------------------------|
| Tax status                         |            |                                     | Valid until 1 February |
| Days left                          |            |                                     | 279                    |
| MOT expiry date                    |            |                                     | 21 December 2024       |
| Full MOT history                   |            |                                     | <u>See MOT history</u> |
| Tax calculation                    |            |                                     |                        |
| Vahiala alaas                      |            | 40                                  |                        |

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | A              |
| Single payment (12 months)              | £ 0,00,-       |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |





#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |
|----------|---------|
| Date     |         |
| Category | Lampe   |
| Туре     |         |
| Damage 2 | AMPLE   |
| Damage 2 | E E E E |
| Date     | S.      |
| Category | ame     |
| Туре     |         |

#### Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





### Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second sec |             |
|--|-------------|
| *************  |             |
| ********   |             |
| ******   |             |
| ************   |             |
| ********   |             |
|  | More info > |
| Plate changes See in this check if this BMW had different number plates  |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Carrent registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |



SD13UAL report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 12         |
| First mileage registration | 2013-04-26 |
| Last registration          | 2023-12-21 |
| Complete history           | See info   |



| Registration #1                    | 2013-04-26 | 16 mi  |
|------------------------------------|------------|--|
| Registration #2                    | 2016-04-12 | 32.493 mi  |
| Registration #3                    | 2016-04-12 | 32.493 mi  |
| Registration #4                    | 2017-04-24 | 43.679 mi  |
| Registration #5                    | 2018-04-05 | 53.964 mi  |
| Registration #6                    | 2019-04-11 | 63.169 mi  |
|                                    |            |  |
| Registration #7                    |            | 11.777 est   |
| Registration #7<br>Registration #8 |            | 11.227 est   |
|                                    |            | 11.777 46<br>11.777 46<br>11.777 46                                |
| Registration #8                    |            | 11,117 46<br>11,177 46<br>11,177 46<br>11,177 46                   |
| Registration #8<br>Registration #9 |            | 00.000 460<br>00.000 460<br>00.000 460<br>00.000 460<br>00.000 460 |






#### Car features

| S0225  | Air conditionin |
|--------|-----------------|
| \$0295 |                 |
| 50482  |                 |
| 50501  |                 |
| 50566  |                 |
| 60567  |                 |
| 60569  |                 |

# Safety ratings

| NCAP rating    | ****                   |
|----------------|------------------------|
| Adult          | 91%                    |
| Children       | 83%                    |
| Pedestrian     | 63%                    |
| Safety systems | 86%                    |
| Overall rating | 83%                    |
| Video          | <u>see crash video</u> |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1765 mm          |
| Height                            | 1421 mm          |
| Length                            | 4324 mm          |
| Wheel base                        | 2690 mm          |
| Kerb weight                       | 1310 kg          |
| Max. allowed weight               | 1840 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 50               |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 5 page 12/12     |

| Number of axles | 2        |
|-----------------|----------|
| Engine number   | 74698428 |