





report date: 2024-03-28

General information

Make	FIAT
Model	500 C POP DUALOGIC
Colour	Red
Year of manufacture	2011
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-04-07


Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-12-19
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	18
Total items failed	2

MOT #11	2023-12-15 16:23
MOT test number	929330678375
Result	✓ Passed
Next expiry date	2024-12-19
Advice Front Brake disc worn, but not excessively Lipped (1.1.14 (a) (i))	
Minor Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))	
Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt	
Advice Rear Coil spring corroded Both	rear springs (5.3.1 (b) (i))

MOT #10	2023-12-15 12:22
MOT test number	791400710823
Result	× Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge Bald on its inner (5.2.3 (e))	edge - 2mm in centre
Minor Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not fur	nctioning (4.3.1 (a) (i))
Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt	
Advice Rear Coil spring corroded Both rear springs (5.3.1 (b) (i))	
Advice Front Brake disc worn, but not excessively Lipped (1.1.14 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge Bald on its inner ed	dge (5.2.3 (e))
Fail Offside Front Lower Suspension arm pin or bush excessively worn Bush bonding suspension arm (5.3.4 (a) (i))	រុ has detached from

CarCheck.co.uk page 3/12



MOT #9 2022-12-16 17:12

MOT test number 164704671725

Result ✓ Passed

Advice Rear Coil spring corroded s (5.3.1 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))

Advice Front suspension top mounts slight play

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Front Brake disc worn, but not excessively s (1.1.14 (a) (i))

MOT #8 2021-12-15 16:49

MOT test number 927011662103

Result \rightarrow Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 185/55/R15 CONTINENTAL (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing 185/55/R15 CONTINENTAL (5.2.3 (d) (ii))

MOT #7 2020-12-15 12:39

MOT test number 382754588284

Result

Passed

MOT #6 2019-12-18 10:29

MOT test number 961089117569

Result

Passed

Advice Exhaust system in poor condition including a leak of gasses from center rear join

MOT #5 2018-11-30 10:53

MOT test number 544361894400

Result

Passed

CarCheck.co.uk page 4/12



MOT #2

MOT test number

RJ60EGK report date: 2024-03-28

2016-01-13 16:28

691632599147

MOT #4		2017-12-20 12:05
MOT test number		669450686875
Result		✓ Passed
MOT #3		2017-12-20 12:05
MOT test number		135132028191
Result		× Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	

Result	✓ Passed
MOT #1	2015-01-05 15:01
MOT test number	385125605063
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners die Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	IR SIE
Plate since	
Current registration	NK.
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-01-27
Last registration	2023-12-15
Complete history	See info



Registration #1	2011-01-27	25 mi
Registration #2	2015-01-05	7.989 mi
Registration #3	2016-01-13	9.330 mi
Registration #4	2017-12-20	11.087 mi
Registration #5	2017-12-20	11.087 mi
Registration #6	2018-11-30	11.840 mi
Registration #7	2019-12-18	12.444 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number6491843