



report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA SVE
Colour	Beige
Year of manufacture	2006
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-27
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-14
MOT pass rate	58 %
MOT passed	15
Failed MOT tests	11
Total advice items	77
Total items failed	26

MOT #26	2023-06-28 15:58
---------	------------------

MOT test number	278151460080
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-14
------------------	------------

Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #25

2023-06-28 14:14

MOT test number

677531480522

Result

✗ Failed

**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))

**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #24**

2022-07-15 15:57

**MOT test number**

715577024460

**Result**

✓ Passed

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear light unit lens cracked**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Front Inner Brake pad(s) wearing thin appear low (1.1.13 (a) (ii))**MOT #23**

2022-07-14 09:09

**MOT test number**

284162312847

**Result**

✗ Failed

**Advice** Front Inner Brake pad(s) wearing thin appear low (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear light unit lens cracked**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #22**

2021-06-26 12:22

**MOT test number**

620290484588

**Result**

✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front antiroll bar bushes perishing bothsides**MOT #21**

2021-06-25 11:05

**MOT test number**

388069450010

**Result**

✗ Failed

**Advice** Front antiroll bar bushes perishing bothsides**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened bothsides (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Parking (secondary brake) on a single line braking system grabbing severely (1.3.1 (c))**MOT #20**

2020-09-29 12:32

**MOT test number**

710548800104

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))

**MOT #19** 2020-09-29 10:32**MOT test number** 206580210880**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #18** 2019-09-25 14:49**MOT test number** 120138545964**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Off side rear tyre tread starting to crack**MOT #17** 2019-09-25 10:19**MOT test number** 735791958482**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Off side rear tyre tread starting to crack**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #16** 2018-09-25 16:10**MOT test number** 986822119398**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2018-09-25 09:33**MOT test number** 706207986618**Result** ✗ Failed**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Brake disc in such a condition that it is seriously weakened both front (1.1.14 (a) (ii))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**MOT #14** 2017-09-26 14:58**MOT test number** 840286903905**Result** ✓ Passed**Advice** Front brake discs corroded



**MOT #13**

2017-09-26 08:57

**MOT test number**

951429853880

**Result****✗ Failed****Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake discs corroded**Fail** Rear parking (secondary) brakes imbalanced (3.7.B.6b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #12**

2016-09-27 14:54

**MOT test number**

478783329126

**Result****✓ Passed****Advice** Tyre worn close to the legal limit both front (4.1.E.1)**MOT #11**

2016-09-27 09:20

**MOT test number**

733034017561

**Result****✗ Failed****Fail** Offside Headlamp aim too low (1.8)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Exhaust system not adequately supported (7.1.1)**Advice** Tyre worn close to the legal limit both front (4.1.E.1)

**MOT #10** 2015-09-09 14:14**MOT test number** 998486272450**Result** ✓ Passed**Advice** Adv both front tyres low**Advice** Adv play in n/s ball joint**MOT #9** 2014-07-26 10:33**MOT test number** 867057304215**Result** ✓ Passed**Notice** Oil leak**MOT #8** 2014-07-26 10:33**MOT test number** 555047104212**Result** ✗ Failed**Notice** Oil leak**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively  
(8.2.2)**MOT #7** 2013-07-13 10:16**MOT test number** 795274893187**Result** ✓ Passed**Notice** Nearside rear tyre cracking**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)

**MOT #6** 2013-07-13 10:16**MOT test number** 227184893448**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nearside rear tyre cracking**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2012-07-12 14:33**MOT test number** 248424892476**Result** ✓ Passed**MOT #4** 2012-07-12 10:29**MOT test number** 387744192142**Result** ✗ Failed**Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Nearside rear brake application uneven (3.7.B.2)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3** 2011-07-14 14:05**MOT test number** 336835091172**Result** ✓ Passed**MOT #2** 2010-08-03 11:26**MOT test number** 250755910266**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1	2009-07-31 11:12
MOT test number	490242519262
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear brake disc slightly scored (3.5.1h)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 July 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	14 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2006-08-05
Last registration	2023-06-28
Complete history	<a href="#">See info</a>



Registration #1	2006-08-05	9 mi
Registration #2	2009-07-31	25.459 mi
Registration #3	2010-08-03	34.454 mi
Registration #4	2011-07-14	40.175 mi
Registration #5	2012-07-12	45.188 mi
Registration #6	2012-07-12	45.188 mi
Registration #7	2013-07-13	50.997 mi
Registration #8	2014-07-26	57.832 mi
Registration #9	2015-09-09	61.504 mi
Registration #10	2016-09-27	63.264 mi
Registration #11	2016-09-27	63.265 mi
Registration #12	2017-09-26	66.174 mi
Registration #13	2017-09-26	66.174 mi
Registration #14	2018-09-26	66.174 mi
Registration #15	2019-09-26	66.174 mi
Registration #16	2020-09-26	66.174 mi
Registration #17	2021-09-26	66.174 mi
Registration #18	2022-09-26	66.174 mi
Registration #19	2023-06-28	66.174 mi
Registration #20	2023-06-28	66.174 mi
Registration #21	2023-06-28	66.174 mi
Registration #22	2023-06-28	66.174 mi
Registration #23	2023-06-28	66.174 mi
Registration #24	2023-06-28	66.174 mi
Registration #25	2023-06-28	66.174 mi
Registration #26	2023-06-28	66.174 mi

**More info** >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1179 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	369789