





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	C C200 K ELEGANCE SE
Colour	Silver
Year of manufacture	-
Top speed	144 mph
0 - 60 mph	9.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	240 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.5 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-10

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT #21		2022-08-10 07:24
MOT test	number	871784373842
Result		✓ Passed
Next exp	iry date	2023-08-09
Advice	Nearside Front fog light doe's not illuminate	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.	1.11 (c))
Minor	Windscreen damaged but not adversely affecting driver's view Stone chip i	n zone 'A' (3.2 (a) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material Greased (1	.1.11 (c))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriously redu	cing light output (4.1.4
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Oil leak, but not excessive Gearbox (8.4.1 (a) (i))	
Advice	Brake pipe corroded, covered in grease or other material Front to rear (1.1	1.11 (c))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reduci	ng light output (4.1.4

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #20 2022-08-02 12:13

MOT test number 600665556861 Result × Failed **Advice** Rear Brake pipe corroded, covered in grease or other material Greased (1.1.11 (c)) Fail Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b)) Offside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i)) **Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i)) Advice Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c)) Advice Nearside Front fog light doe's not illuminate **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view Stone chip in zone 'A' (3.2 (a) (i))

Fail Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #19 2021-08-06 16:31 **MOT** test number 195483718930 Result ✓ Passed **Advice** Gearbox oil leak Advice Front tyres worn Advice Headlamps discoloured Advice Front indicators showing white light Advice N/s/f fog lamp inoperative Advice Brake pipe corrosion o/s/f

MOT #18

MOT test number

Result

Minor Front Headlamp lens slightly defective both sides (4.1.1 (b) (i))

MOT #17 2019-06-20 14:22 **MOT** test number 750254683181 Result Passed **Advice** Offside Rear Brake hose slightly deteriorated flexi hose (1.1.12 (b) (ii)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Brake hose slightly deteriorated flexi hose (1.1.12 (b) (ii)) Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 5/15



YBO3WAA
report date: 2024-03-28

MOT #16 2018-06-08 09:55

MOT test number 368779994266

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2017-05-27 07:34

MOT test number 548618997193

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Engine light on

CarCheck.co.uk page 6/15



MOT #14

Fail

Fail

Fail

Advice

Advice

Fail

Engine light on

YB03WAA

report date: 2024-03-28

2017-05-25 12:46

MOT test number 543062141130 Result × Failed Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b) Fail Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3) Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Nearside Rear position lamp(s) not working (1.1.A.3b) Fail **Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c) Fail Offside Registration plate lamp not working (1.1.C.1d) Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Nearside Headlamp not working on dipped beam (1.7.5a)

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

Offside Rear position lamp(s) not working (1.1.A.3b)

Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #13 2016-05-24 09:26

MOT test number 593545685947

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #12	2015-06-09 09:20
MOT test number	695710065106
Result	✓ Passed
Notice Very slight oil "sweting" around gearbox sump	

MOT #11		2014-06-11 10:28
MOT test	number	978532064136
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #10	2013-12-17 09:09
MOT test number	329251053363
Result	✓ Passed
MOT #9	2012-12-18 09:49
MOT test number	695293052393
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

child seat fitted flot allowing fall inspection of addit self	
MOT #8	2011-12-13 13:57
MOT test number	365037141327
Result	✓ Passed
MOT #7	2010-12-10 13:57
MOT test number	633804240356
Result	✓ Passed

CarCheck.co.uk page 8/15



YBO3WAA
report date: 2024-03-28

MOT test number

Fail Nearside Rear coil spring fractured (2.4.C.1a)

Fail Offside Front coil spring fractured (2.4.C.1a)

Fail Offside Rear coil spring fractured (2.4.C.1a)

Fail Offside Rear coil spring fractured (2.4.C.1a)	
MOT #5	2009-12-15 10:47
MOT test number	761259249386
Result	✓ Passed
MOT #4	2008-12-18 13:31
MOT test number	744353658300
Result	✓ Passed
MOT #3	2007-12-19 11:28
MOT test number	702333157388
Result	✓ Passed
MOT #2	2006-12-21 12:03
MOT test number	870235356382
Result	✓ Passed

MOT #1	2006-06-08 12:47
MOT test number	202149556107
Result	✓ Passed

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

More info >

Owner history

C Wile Prince of	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-06-26
Last registration	2022-08-10
Complete history	See info



Registration #1	2003-06-26	26 mi
Registration #2	2006-06-08	28.843 mi
Registration #3	2006-12-21	32.018 mi
Registration #4	2007-12-19	40.761 mi
Registration #5	2008-12-18	49.539 mi
Registration #6	2009-12-15	59.144 mi
Registration #7	2010-12-09	65.837 mi
Registration #8	2010-12-10	65.837 mi
Registration #9	2011-12-13	73.138 mi
Registration #10	2012-12-18	78.501 mi
Registration #11	2013-12-17	83.330 mi
Registration #12	2014-06-11	85.060 mi
Registration #13		11.177 es
Registration #14		11.177 ea
Registration #15		11.177 es
Registration #16		
negistration # 10		71.777 es
Registration #17		11.777 es
-		11.777 ea 11.777 ea
Registration #17		11.777 ea 11.777 ea 11.777 ea
Registration #17 Registration #18		11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #17 Registration #18 Registration #19		11.777 es 11.777 es 11.777 es 11.777 es
Registration #17 Registration #18 Registration #19 Registration #20		11.777-66 11.777-66 11.777-66 11.777-66 11.777-66

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
60501	
60566	
60567	
60569	

Dimensions & weight

Width	1956 mm
Height	1426 mm
Length	4526 mm
Wheel base	2715 mm
Kerb weight	1970 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	27194030074585

CarCheck.co.uk page 15/15