





report date: 2024-03-29

General information

Make	TOYOTA
Model	AVENSIS D-4D T4
Colour	Blue
Year of manufacture	2009
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/15



CK59DZA

report date: 2024-03-29

Internet history


Entry 1


Date 2021-09-01


Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-07-05
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	40
Total items failed	9

MOT #18		2023-07-06 11:35
MOT test	number	112802234357
Result		✓ Passed
Next expiry date 2024-07		2024-07-05
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))	

MOT #17	2023-06-28 14:11
MOT test number	262001518092
Result	X Failed
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps (4.7.1 (b) (i))	or light sources
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))	

MOT #16	2022-07-05 09:34
MOT test number	230242450215
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/15



Advice

CK59DZA

report date: 2024-03-29

MOT #15 2021-08-26 11:57 915509083255 **MOT** test number ✓ Passed Result **MOT #14** 2021-08-25 10:34 **MOT** test number 820090052699 Result × Failed Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2020-08-24 15:01 **MOT** test number 531864380031 Result Passed **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b)) Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/15



Advice

CK59DZA

report date: 2024-03-29

MOT #12 2020-08-24 08:48 656402440829 **MOT** test number Result × Failed **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail Fail Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i)) Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11		2019-08-08 10:02
MOT test	number	797125291900
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Rear Nail in tyre	
Advice	All suspension components corroded but not exessive	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 5/15



MOT #10 2019-08-08 10:02

MOT test number 270228303247

Result X Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Nail in tyre

Advice All suspension components corroded but not exessive

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2018-08-10 12:52

MOT test number 950321567602

Advice (All) suspension has surface rust

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing

arm (5.3.4 (a) (i))

Advice Front Brake discs becoming lipped

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing

arm (5.3.4 (a) (i))

Advice Nearside Rear Tyre deteriorated

MOT #8 2017-08-10 11:26

MOT test number 100625718392

Result ✓ Passed

CarCheck.co.uk page 6/15



MOT #7

MOT test number

Result

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #6	2016-08-08 10:25
MOT test number	280233960342
Result	✓ Passed
MOT #5	2015-08-25 07:44
MOT test number	845950388134
Result	✓ Passed
MOT #4	2015-08-25 00:00
MOT test number	271719705720
Result	✓ Passed
MOT #3	2014-08-26 16:03
MOT test number	997378734229
Result	✓ Passed
MOT #2	2013-08-30 11:16
MOT test number	697742443293
Result	✓ Passed

CarCheck.co.uk page 7/15



MOT #1 2012-10-01 14:44

MOT test number 317795372255

Result
✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front brake juddering slightly (3.7.A.2b)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 9/15



CK59DZA

report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

,		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		OTA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



CK59DZA

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-09-30
Last registration	2023-07-06
Complete history	See info



Registration #1	2009-09-30	25 mi
Registration #2	2012-10-01	30.499 mi
Registration #3	2013-08-30	39.517 mi
Registration #4	2014-08-26	49.139 mi
Registration #5	2015-08-25	58.524 mi
Registration #6	2015-08-25	58.524 mi
Registration #7	2016-08-08	61.479 mi
Registration #8	2017-08-10	67.236 mi
Registration #9	2017-08-10	67.236 mi
Registration #10	2018-08-10	73.710 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
•		

More info >

CarCheck.co.uk page 14/15



Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4765 mm
Wheel base	2700 mm
Kerb weight	1635 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 15/15

Number of axles 2

Engine number 1AF5439178