



report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI T-SPEC
Colour	Grey
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	172 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-10-16
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	57 %
MOT passed	17
Failed MOT tests	13
Total advice items	63
Total items failed	45

MOT #30	2024-01-31 18:39
MOT test number	936902132377
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bushes both (5.3.4 (a) (i))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #29**

2024-01-25 11:07

MOT test number

231707154068

Result

✗ Failed

- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bushes both (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #28

2023-01-23 13:30

MOT test number

419799689509

Result

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #27

2022-01-28 11:47

MOT test number

417943954141

Result

✓ Passed

**MOT #26**

2022-01-25 16:17

MOT test number

106964047519

Result

✗ Failed

Fail Brake pedal anti-slip provision worn smooth (1.1.2 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #25**

2022-01-20 08:51

MOT test number

955737248637

Result

✗ Failed

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** High level brake light covered in stickers**MOT #24**

2020-12-17 15:18

MOT test number

533588506847

Result

✓ Passed

Advice Both chassis rails corroded**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Central Rear Upper Brake light covered with stickers

**MOT #23**

2020-12-17 12:21

MOT test number

403969916719

Result**✗ Failed****Advice** Central Rear Upper Brake light covered with stickers**Advice** Both chassis rails corroded**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Tyre has ply or cords exposed 255/65r17 110t (5.2.3 (d) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Wearing on edges 2 mm (5.2.3 (e))**MOT #22**

2019-12-12 10:22

MOT test number

762293256620

Result**✓ Passed****Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Brake Pedal Appears Long in Travel**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #21**

2019-12-12 09:17

MOT test number

492156028029

Result**✗ Failed****Fail** Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Brake Pedal Appears Long in Travel

**MOT #20** 2018-11-30 09:56**MOT test number** 659258376416**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #19** 2018-11-28 09:16**MOT test number** 840336727864**Result** ✗ Failed**Fail** Nearside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))**MOT #18** 2017-11-27 09:16**MOT test number** 863137357227**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit Worn Inner Edge (4.1.E.1)**Advice** Offside Rear Door Appears Tight To Open/Close**MOT #17** 2016-12-01 15:02**MOT test number** 679695207470**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #16** 2016-11-30 09:28**MOT test number** 188611505012**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear Tyre has ply or cords exposed 255/65/17 110H (4.1.D.1b)

MOT #15 2015-12-17 12:50**MOT test number** 202414192179**Result** ✓ Passed**MOT #14** 2015-12-16 10:32**MOT test number** 136738838474**Result** ✗ Failed

- Advice** Oil leak
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Nearside Rear Anti-roll bar has excessive play in a ball joint link (2.4.G.2)

MOT #13 2015-08-13 10:14**MOT test number** 852112336490**Result** ✓ Passed**MOT #12** 2014-08-14 12:10**MOT test number** 497866024235**Result** ✓ Passed



MOT #11 2014-08-11 14:53

MOT test number 389363624215

Result ✗ Failed

Notice Oil leak

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #10 2013-08-02 12:17

MOT test number 826694913262

Result ✓ Passed

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)

Notice Oil leak

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2012-06-06 17:07

MOT test number 855188852105

Result ✓ Passed

**MOT #8**

2012-05-30 11:15

MOT test number

268421152465

Result**✗ Failed**

- Fail** Front registration plate missing (6.3.1a)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
- Notice** Headlamp masks/converters fitted to offside
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Nearside Rear Statutory seat belt missing (5.1.1)
- Notice** Spare wheel in interior
- Fail** Offside Front Headlamp aim too low (1.8)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)
- Fail** Front Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Centre Rear Statutory seat belt missing (5.1.1)
- Notice** Nail in nearside rear tyre
- Fail** Nearside Front Headlamp aim too low (1.8)
- Fail** Offside Rear Statutory seat belt missing (5.1.1)
- Fail** Driver's door cannot be opened from inside the vehicle (6.2.B.1b)

**MOT #7** 2011-06-03 17:33**MOT test number** 296454651109**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Notice** Offside rear door not opening from the outside.**Notice** Rear wiper deteriorated.**MOT #6** 2011-06-03 10:34**MOT test number** 788564851136**Result** ✗ Failed**Notice** Rear wiper deteriorated.**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Notice** Offside rear door not opening from the outside.**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #5** 2010-05-21 12:42**MOT test number** 394211740111**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-07-15 12:19**MOT test number** 273836599194**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**MOT #3** 2009-07-14 15:15**MOT test number** 922445699169**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2008-05-27 15:17**MOT test number** 690748548100**Result** ✓ Passed**MOT #1** 2008-05-27 12:14**MOT test number** 274178948189**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	32
First mileage registration	2005-03-24
Last registration	2024-01-31
Complete history	See info



Registration #1	2005-03-24	18 mi
Registration #2	2008-05-27	15.253 mi
Registration #3	2008-05-27	15.253 mi
Registration #4	2009-07-14	30.518 mi
Registration #5	2009-07-15	30.526 mi
Registration #6	2010-05-21	44.399 mi
Registration #7	2011-06-03	58.214 mi
Registration #8	2011-06-03	58.224 mi
Registration #9	2012-05-30	70.936 mi
Registration #10	2012-06-06	70.951 mi
Registration #11	2013-08-02	86.487 mi
Registration #12	2014-08-11	99.960 mi
Registration #13	2014-08-14	99.969 mi
Registration #14	2015-08-13	111.259 mi
Registration #15	2015-12-16	115.422 mi
Registration #16	2015-12-17	115.422 mi
Registration #17	2016-05-20	121.277 mi
Registration #18	2016-05-20	121.277 mi
Registration #19	2016-05-20	121.277 mi
Registration #20	2016-05-20	121.277 mi
Registration #21	2016-05-20	121.277 mi
Registration #22	2016-05-20	121.277 mi
Registration #23	2016-05-20	121.277 mi
Registration #24	2016-05-20	121.277 mi
Registration #25	2016-05-20	121.277 mi
Registration #26	2016-05-20	121.277 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442
Registration #30	2025-25-25	25,252,442
Registration #31	2025-25-25	25,252,442
Registration #32	2025-25-25	25,252,442

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1850 mm
Height	1783 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2267 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	607671