





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 сс
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L



CarCheck.co.uk page 1/13



Internet history

Entry	1

Lifety 1	
Date	2021-09-14
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-08-23
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	31
Total items failed	4

MOT #14	2023-08-10 13:49
MOT test number	843771655710
Result	✓ Passed
Next expiry date	2024-08-23
Advice Nearside Front Outer Tyre slightly damaged sidewall (5.2.3 (d) (ii))	

MOT #13	2023-08-1	10 09:43
MOT test i	number 473764	4805370
Result		X Failed
Advice	Nearside Front Outer Tyre slightly damaged sidewall (5.2.3 (d) (ii))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Central Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii	i))

MOT #12	2022-08-13 08:52
MOT test number	983446257585
Result	✓ Passed
Advice Air con leak	

CarCheck.co.uk page 3/13



LR62FTV

report date: 2024-03-29

MOT #11

MOT test number

721828809380

Result

Pass with rectification

Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Air con leak

Pass with rectification
functioning (4.3.1 (a) (ii))

Central Rear Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (iii))

 MOT #10
 2021-08-24 14:59

 MOT test number
 170996330477

 Result
 ✓ Passed

 MOT #9
 2020-01-09 14:35

 MOT test number
 692992190425

 Result
 ✓ Passed

MOT test number

Result

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



LR62FTV

report date: 2024-03-29

MOT #7 2019-09-12 10:05 **MOT** test number 192582574519 Result **X** Failed **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Pass with rectification Brake lever has insufficient reserve travel (1.1.2 (a)) Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2018-12-27 18:13 835931217454 **MOT** test number Result Passed **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** HANDBRAKE PARKING LEVER HAS LITTLE RESERVE TRAVEL Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #5		2018-08-04 13:35
MOT test	number	679177891500
Result		✓ Passed
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 5/13



MOT #4 2017-11-15 11:16

MOT test number 835635980476

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2017-11-15 11:16

MOT test number 752494104071

Result X Failed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Nearside Front Battery insecure (1.9.1)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2015-11-25 12:12

MOT test number 488617379094

Result
✓ Passed

MOT #1 2014-11-27 16:16

MOT test number 898761834312

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Plate since

LR62FTV

report date: 2024-03-29

More info >

Owner history		
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full re		IAC

	More info >	
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since	1999	m m
Formed modulostics	SE C	

CarCheck.co.uk page 10/13



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-10-25
Last registration	2023-08-10
Complete history	See info



Registration #1	2012-10-25	21 mi
Registration #2	2014-11-27	26.039 mi
Registration #3	2015-11-25	33.051 mi
Registration #4	2017-11-15	34.828 mi
Registration #5	2017-11-15	34.828 mi
Registration #6	2018-08-04	42.625 mi
Registration #7	2018-12-27	48.279 mi
Registration #8	2019-09-12	54.907 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 mg

More info >

page 12/13 CarCheck.co.uk



LR62FTV

report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	8	page 13/13