



HONDA




report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	White
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-01-12
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-27
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	25
Total items failed	1

MOT #10	2023-09-26 10:02
MOT test number	383962725694
Result	✓ Passed
Next expiry date	2024-09-27
Advice	Rear axle corroded, not considered excessive
Advice	Suspension component mounting prescribed area is corroded but not considered excessive all (5.3.6 (a) (i))
Advice	Coil spring corroded all (5.3.1 (b) (i))
Advice	Axle Prescribed area corroded, not considered excessive
Advice	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #9** 2023-09-15 09:00**MOT test number** 729136380487**Result** ✗ Failed

- Advice** Offside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Axle Prescribed area corroded, not considered excessive
- Advice** Nearside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive all (5.3.6 (a) (i))
- Advice** Coil spring corroded all (5.3.1 (b) (i))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear axle corroded, not considered excessive

MOT #8 2022-09-28 09:50**MOT test number** 601621695877**Result** ✓ Passed**MOT #7** 2021-09-10 16:09**MOT test number** 297561499097**Result** ✓ Passed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2020-09-18 14:55**MOT test number** 148007049384**Result** ✓ Passed

**MOT #5** 2018-03-26 13:25**MOT test number** 476440360202**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2017-03-25 09:59**MOT test number** 217228889160**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-02-15 11:46**MOT test number** 154380538845**Result** ✓ Passed**MOT #2** 2015-03-06 17:09**MOT test number** 749415165035**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Notice** Under-trays fitted obscuring some underside components



MOT #1 2014-03-11 13:31

MOT test number 175550474051

Result ✓ Passed

- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Lower Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
27 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-03-07
Last registration	2023-09-26
Complete history	See info



Registration #1	2011-03-07	18 mi
Registration #2	2014-03-11	51.833 mi
Registration #3	2015-03-06	70.161 mi
Registration #4	2016-02-15	25.544 mi
Registration #5	2017-03-25	82.354 mi
Registration #6	2018-03-26	86.901 mi
Registration #7	2019-03-27	91.277 mi
Registration #8	2020-03-27	95.277 mi
Registration #9	2021-03-27	99.277 mi
Registration #10	2022-03-27	103.277 mi
Registration #11	2023-03-27	107.277 mi
Registration #12	2024-03-27	111.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1004814