



report date: 2024-03-29

General information

Make	KIA
Model	SEDONA CRDI 2
Colour	Silver
Year of manufacture	2009
0 - 60 mph	11.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	192 BHP
Max. torque	421 Nm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	35.8 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 3

Date 2022-03-30

Pictures 12

Listing price [View report](#)




source: cargurus.co.uk

Entry 2

Date 2021-12-31

Pictures 31

Listing price [View report](#)



source: autotrader.co.uk

Entry 1

Date 2021-12-18

Pictures 32

Listing price [View report](#)



source: cargurus.co.uk

**MOT history**

MOT expiry date	2025-02-07
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	23
Total items failed	13

MOT #17	2024-02-08 11:02
MOT test number	384999205289
Result	✓ Passed
Next expiry date	2025-02-07

MOT #16	2023-02-02 12:40
MOT test number	548157133845
Result	✓ Passed

MOT #15	2022-02-08 14:10
MOT test number	744032271349
Result	✓ Passed

MOT #14	2022-02-07 16:38
MOT test number	486373017078

Result	✗ Failed
---------------	----------

- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #13**

2020-12-30 10:46

MOT test number

362903568345

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge showing 2.3mm - worn inner edge - 225/70 r16 103h (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #12

2020-01-06 11:03

MOT test number

381886962025

Result

✓ Passed

Minor Nearside Rear Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))

MOT #11

2019-01-07 14:29

MOT test number

516273881447

Result

✓ Passed

MOT #10

2019-01-07 12:28

MOT test number

838957067243

Result

✗ Failed

Fail Offside Headlamp aim not tested (4.1.2 (b))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Side repeater incorrect colour (4.4.3 (a))

**MOT #9** 2018-01-03 10:11**MOT test number** 487499151453**Result** ✓ Passed

- Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Rear coil springs corroded

MOT #8 2017-01-05 16:05**MOT test number** 136371610347**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT #7 2017-01-05 11:59**MOT test number** 735835035331**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

MOT #6 2015-12-14 14:38**MOT test number** 194441418523**Result** ✓ Passed

- Advice** Engine oil leak

**MOT #5** 2015-01-08 16:25**MOT test number** 169298205468**Result** ✓ Passed**MOT #4** 2015-01-08 10:35**MOT test number** 539468605046**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Passengers front tyre worn inner edge**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2013-12-03 09:35**MOT test number** 656347633311**Result** ✓ Passed**Notice** O/s/r tyre low**Notice** Front pads low**MOT #2** 2013-01-03 15:17**MOT test number** 817973103087**Result** ✓ Passed**Notice** Unable to see rear brake pads clearly**Notice** Nail in nearside rear tyre**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #12013-01-03 14:39

MOT test number955853603073

Result		✗ Failed
Notice	Nail in nearside rear tyre	
Notice	Child seat fitted not allowing full inspection of adult belt	
Fail	Nearside Headlamp not working on dipped beam (1.7.5a)	
Notice	Unable to see rear brake pads clearly	



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
7 February 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	LV59TXX
Plate since	2019-09-29
Current registration	LV59TXX
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-12-23
Last registration	2024-02-08
Complete history	See info



Registration #1	2009-12-23	25 mi
Registration #2	2013-01-03	35.091 mi
Registration #3	2013-01-03	35.091 mi
Registration #4	2013-12-03	48.092 mi
Registration #5	2015-01-08	63.083 mi
Registration #6	2015-01-08	63.083 mi
Registration #7	2015-12-14	74.802 mi
Registration #8	2017-01-05	88.727 mi
Registration #9	2017-01-05	88.727 mi
Registration #10	2018-01-03	97.611 mi
Registration #11	2019-01-07	109.576 mi
Registration #12	2020-01-07	121.541 mi
Registration #13	2020-01-07	121.541 mi
Registration #14	2020-01-07	121.541 mi
Registration #15	2020-01-07	121.541 mi
Registration #16	2020-01-07	121.541 mi
Registration #17	2020-01-07	121.541 mi
Registration #18	2020-01-07	121.541 mi
Registration #19	2020-01-07	121.541 mi
Registration #20	2020-01-07	121.541 mi
Registration #21	2020-01-07	121.541 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1760 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2025 kg
Max. allowed weight	2810 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	D4HB9U035097