



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	C 350 CDI BLUEEFFICIENCY SPORT
Colour	Red
Year of manufacture	2010
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	265 BHP
Max. torque	620 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-02
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	19
Total items failed	15

MOT #17	2024-04-03 09:42
MOT test number	369448417626
Result	✓ Passed
Next expiry date	2025-04-02

MOT #16	2024-03-25 14:44
MOT test number	144680678729
Result	✗ Failed
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #15	2023-03-17 15:13
MOT test number	843004165164
Result	✓ Passed

MOT #14	2022-03-11 12:05
MOT test number	723299411664
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #13**

2021-02-13 13:15

MOT test number

298828275401

Result

✓ Passed

Advice

Under body covers fitted

MOT #12

2021-02-10 16:44

MOT test number

309601619661

Result

✗ Failed

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice

Under body covers fitted

MOT #11

2020-10-13 10:39

MOT test number

924229640563

Result

✗ Failed

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #10

2019-05-31 16:01

MOT test number

106471809507

Result

✓ Passed

Advice

Items removed from driver's view prior to test

Advice

Park brake only just met requirement, further investigation may be reqd

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9**

2019-05-29 11:40

MOT test number

323673177801

Result

✗ Failed

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt rear arm (5.3.4 (b) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt Forward arm (5.3.4 (b) (ii))

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt forward arm (5.3.4 (b) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Items removed from driver's view prior to test

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt Rear arm (5.3.4 (b) (ii))

MOT #8

2018-07-11 15:06

MOT test number

153844130654

Result

✓ Passed

Advice Nearside Front Brake pipe corroded, covered in grease or other material to flexi hose, slight corrosion (1.1.11 (c))

MOT #7

2018-06-28 10:19

MOT test number

504136198887

Result

✗ Failed

Fail Offside Front Brake pipe excessively corroded to flexi hose (1.1.11 (c))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Offside Headlamp aim too low headlamp not seated correctly (4.1.2 (a))

Advice Offside Rear Brake pipe corroded, covered in grease or other material to flexi hose, slight corrosion (1.1.11 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material to flexi hose, slight corrosion (1.1.11 (c))

Fail Nearside Rear Brake pipe excessively corroded to flexi hose (1.1.11 (c))

**MOT #6** 2017-07-06 13:07**MOT test number** 863435729612**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2016-07-12 12:54**MOT test number** 294437799134**Result** ✓ Passed**MOT #4** 2015-06-11 12:16**MOT test number** 786482265181**Result** ✓ Passed**Notice** O/s fog lamp broken**MOT #3** 2015-06-08 11:42**MOT test number** 316609055182**Result** ✗ Failed**Fail** Offside Front Road wheel bead rim badly distorted (4.2.A.1a)**Notice** O/s fog lamp broken**MOT #2** 2014-05-22 10:04**MOT test number** 978222744106**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2013-05-31 12:57
MOT test number	208321253497
Result	✓ Passed
<div>Notice Offside rear tyre has slight cut in wall, not through to cord or ply.</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
2 April 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 SV10FNK
Plate since	2019-06-29
Current registration	 SV10FNK
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-14
Last registration	2024-04-03
Complete history	See info



Registration #1	2010-06-14	9 mi
Registration #2	2013-05-31	18.104 mi
Registration #3	2014-05-22	32.464 mi
Registration #4	2015-06-08	50.293 mi
Registration #5	2015-06-11	50.675 mi
Registration #6	2016-07-12	77.864 mi
Registration #7	2017-07-06	96.621 mi
Registration #8	2018-06-28	102.128 mi
Registration #9	2018-07-11	102.134 mi
Registration #10	2019-05-29	105.179 mi
Registration #11	2019-05-29	105.179 mi
Registration #12	2019-05-29	105.179 mi
Registration #13	2019-05-29	105.179 mi
Registration #14	2019-05-29	105.179 mi
Registration #15	2019-05-29	105.179 mi
Registration #16	2019-05-29	105.179 mi
Registration #17	2019-05-29	105.179 mi
Registration #18	2019-05-29	105.179 mi
Registration #19	2019-05-29	105.179 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2008 mm
Height	1447 mm
Length	4591 mm
Wheel base	2760 mm
Kerb weight	1750 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64283041030874