





report date: 2024-03-29

### General information

Make	ABARTH
Model	595 595 COMPETIZIONE
Colour	White
Year of manufacture	2016
Top speed	140 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	177 BHP
Max. torque	250 Nm at 3.000 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



## Internet history

### Entry 1

Date 2021-07-03

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-28
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	18
Total items failed	0

MOT #6	2023-06-24 08:04
MOT test number	142413219568
Result	✓ Passed
Next expiry date	2024-06-28

MOT #5		2022-06-27 07:59
MOT test	number	492580040730
Result		✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Rear rear exhaust box outer skin corroded.	

MOT #4	2021-06-29 13:48
MOT test number	986962921262
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



**VE66RRX** 

report date: 2024-03-29

× Failed

MOT #3 2020-11-24 11:29

**MOT test number** 566978673179

**Result** ✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))

1104116 (3.3.1 (4) (1))

**Advice** 

Result

MOT #2 2020-11-23 12:24

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT test number** 693413273105

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



**VE66RRX** 

report date: 2024-03-29

**MOT #1** 2019-11-19 15:26

**MOT test number** 690134132218

**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn low on inner edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn low on inner edge (5.2.3 (e))

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	28 June 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



#### Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



**VE66RRX** 

report date: 2024-03-29

## Owner history

•	
For how long did the current and previous owner(s) have this ABARTH? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	
*******	
***************************************	
	More info >
Plate changes	
See in this check if this ABARTH had different number plates.	
Number of plates	,
Current registration	OK SIE
Flate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled.

If not, and you buy this ABARTH then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this ABARTH is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-12-09
Last registration	2023-06-24
Complete history	See info



Registration #1	2016-12-09	12 mi
Registration #2	2019-11-19	21.480 mi
Registration #3	2020-11-23	28.710 mi
Registration #4	2020-11-24	28.710 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 11/12



			_		
- 1	man	CIAN	C A.	WOL	thr
ווט		וטוכו	אט כו	weig	וווע

Width	1627 mm
Height	1485 mm
Length	3660 mm
Wheel base	2300 mm
Kerb weight	1070 kg
Max. allowed weight	1425 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	2105700

CarCheck.co.uk page 12/12