



PEUGEOT



report date: 2024-03-28

General information

| | |
|---------------------|-----------------|
| Make | PEUGEOT |
| Model | 5008 HDI ACTIVE |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 115 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 115 BHP |
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 128 g/km |
| CO2 label | D |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-15 |
| Pictures | 44 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-10 |
| MOT pass rate | 64 % |
| MOT passed | 7 |
| Failed MOT tests | 4 |
| Total advice items | 8 |
| Total items failed | 2 |

| | |
|------------------|------------------|
| MOT #11 | 2023-05-16 14:22 |
| MOT test number | 383692228496 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-10 |

| | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| MOT #10 | 2023-05-16 08:22 |
| MOT test number | 101155120329 |
| Result | ✗ Failed |
| <p>DANGEROUS Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))</p> <p>MAJOR Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))</p> | |

| | |
|-----------------|------------------|
| MOT #9 | 2022-05-24 13:36 |
| MOT test number | 428290501197 |
| Result | ✓ Passed |

**MOT #8** 2022-05-24 08:15**MOT test number** 887195377193**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #7** 2021-06-11 13:49**MOT test number** 400955737110**Result** ✓ Passed**MOT #6** 2020-08-12 10:26**MOT test number** 828015157027**Result** ✓ Passed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #5** 2020-08-12 10:26**MOT test number** 341738746441**Result** ✗ Failed**Pass with rectification** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #4** 2019-08-02 13:30**MOT test number** 595552270697**Result** ✓ Passed



| | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| MOT #3 | 2018-08-15 13:02 |
| MOT test number | 945013561130 |
| Result | ✓ Passed |
| MOT #2 | 2018-02-01 11:55 |
| MOT test number | 172818757963 |
| Result | ✓ Passed |
| MOT #1 | 2018-02-01 10:57 |
| MOT test number | 774284269894 |
| Result | ✗ Failed |
| <div><div>Fail</div><div>Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)</div></div> | |



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
10 June 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 10 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|-----------------------------------------|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 5 |
| Current registration | MA15WMX |
| Plate since | 2019-09-28 |
| Current registration | MA15WMX |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2015-03-30 |
| Last registration | 2023-05-16 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-03-30 | 24 mi |
| Registration #2 | 2018-02-01 | 30.466 mi |
| Registration #3 | 2018-02-01 | 30.466 mi |
| Registration #4 | 2018-08-15 | 34.850 mi |
| Registration #5 | 2019-08-02 | 42.528 mi |
| Registration #6 | 2020-08-12 | 53.090 mi |
| Registration #7 | 2020-08-12 | 53.090 mi |
| Registration #8 | 2023-05-16 | 53.090 mi |
| Registration #9 | 2023-05-16 | 53.090 mi |
| Registration #10 | 2023-05-16 | 53.090 mi |
| Registration #11 | 2023-05-16 | 53.090 mi |
| Registration #12 | 2023-05-16 | 53.090 mi |
| Registration #13 | 2023-05-16 | 53.090 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 79% |
| Pedestrian | 37% |
| Safety systems | 97% |
| Overall rating | 77% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1837 mm |
| Height | 1647 mm |
| Length | 4529 mm |
| Wheel base | 2727 mm |
| Kerb weight | 1430 kg |
| Max. allowed weight | 2250 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|-----------------|-------------|
| Number of axles | 2 |
| Engine number | JBER0190221 |