



General information

| | |
|---------------------|---------------------------------------|
| Make | VOLKSWAGEN |
| Model | SCIROCCO GT TSI BLUEMOTION TECHNOLOGY |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 126 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|--------------------------|
| Power | 92 kW / 125 HP / 123 BHP |
| Max. torque | 280 Nm at 1.400 rpm |
| Engine capacity | 1.395 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 41.5 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 52.3 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |






Internet history

Entry 3

Date 2023-12-14

Pictures 8



source: g3remarketing.co.uk

Entry 2

Date 2023-02-05

Pictures 17

Listing price [View report](#)






source: autotrader.co.uk

Entry 1

Date 2021-12-06

Pictures 54

Listing price [View report](#)



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-06 |
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 1 |
| Total items failed | 1 |

| | |
|------------------|------------------|
| MOT #7 | 2024-03-07 12:48 |
| MOT test number | 207350880519 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-06 |

| | |
|-----------------|------------------|
| MOT #6 | 2023-02-01 09:15 |
| MOT test number | 541878892280 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #5 | 2021-12-07 17:04 |
| MOT test number | 673749955032 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #4 | 2021-01-29 12:19 |
| MOT test number | 890950561960 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #3 | 2021-01-29 12:19 |
| MOT test number | 256783316995 |
| Result | ✗ Failed |

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))



| | |
|-----------------|---|
| MOT #2 | 2020-01-16 12:26 |
| MOT test number | 826862723200 |
| Result | ✓ Passed |
| Advice | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |

| | |
|-----------------|------------------|
| MOT #1 | 2019-01-18 16:12 |
| MOT test number | 535145706905 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 6 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2016-03-31 |
| Last registration | 2024-03-07 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2016-03-31 | 16 mi |
| Registration #2 | 2019-01-18 | 14.268 mi |
| Registration #3 | 2020-01-16 | 27.434 mi |
| Registration #4 | 2021-01-29 | 49.596 mi |
| Registration #5 | 2021-01-29 | 49.596 mi |
| Registration #6 | 2022-03-29 | 55.277 mi |
| Registration #7 | 2022-03-29 | 55.277 mi |
| Registration #8 | 2022-03-29 | 55.277 mi |
| Registration #9 | 2022-03-29 | 55.277 mi |
| Registration #10 | 2024-03-07 | 55.277 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 73% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1404 mm |
| Length | 4256 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1318 kg |
| Max. allowed weight | 1680 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |

| | |
|-----------------|------------|
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | CZCA619609 |