





report date: 2024-03-28

#### General information

Make	VOLVO
Model	V40 D2 MOMENTUM
Colour	Bronze
Year of manufacture	2016
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	118 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	70.6 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	89 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-03-16
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #8	2024-03-06 15:39
MOT test number	227276171001
Result	<b>✓</b> Passed
Next expiry date	2025-03-16

MOT #7	2023-03-13 15:00
MOT test number	276172968651
Result	<b>✓</b> Passed
Advice Offside Front Inner Play in steering rack inner joint(s)	

MOT #6	2023-03-07 15:25
MOT test number	452930904079
Result	<b>X</b> Failed
Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))  Advice Offside Front Inner Play in steering rack inner joint(s)	

CarCheck.co.uk page 3/11



MOT #2

**RE66NUV** 

report date: 2024-03-28

2020-08-03 14:07

MOT #5		2022-03-15 10:17
MOT test	number	796602389703
Result		✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Front Play in steering rack inner joint(s)	
Advice	Nearside Front Play in steering rack inner joint(s)	

MOT #4	2021-03-17 14:04
MOT test number	360780447472
Result	<b>✓</b> Passed
Advice Engine cover and undertray fitted	

MOT #3	2021-03-17 13:13
MOT test number	687970679647
Result	<b>X</b> Failed
Advice Engine cover and undertray fitted	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT test number	817921536725
Result	✓ Passed
MOT #1	2019-08-29 15:03
MOT test number	250408864706
Result	✓ Passed
Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	16 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

e when moterly	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
********	
***************************************	
**********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	IR SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-11-11
Last registration	2024-03-06
Complete history	See info



Registration #1	2016-11-11	27 mi
Registration #2	2019-08-29	46.919 mi
Registration #3	2020-08-03	65.078 mi
Registration #4		11.777 es
Registration #5	2021-03-17	70.109 mi
_		
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
		11.77 m
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



# Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1423 kg
Max. allowed weight	1920 kg

# Additional information

Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11,

Number of axles2Engine number1702307