





General information

Make	AUDI
Model	TT TTS TFSI QUATTRO
Colour	Grey
Year of manufacture	2010
Top speed	155 mph
0 - 60 mph	5.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	272 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	35.8 mpg
CO2 emission	184 g/km
CO2 label	I







Internet history

_

Entry 3	
Date	2021-11-04
Pictures	80
Listing price	View report



source: yesauto.com

E	n	tr	У	2

Date

Pictures

Listing price

2021-09-23 12

View report



source: cargurus.co.uk

Entry 1

Date	2021-09-22	
Pictures	19	
Listing price	View report	









source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-21
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #15	2023-12-07 11:52
MOT test number	925783384702
Result	✓ Passed
Next expiry date	2024-12-21

MOT #14	2022-12-15 12:33
MOT test number	434911234245
Result	✓ Passed

MOT #13	2021-12-22 11:12
MOT test number	373125226838
Result	✓ Passed

MOT #12		2021-09-08 06:57
MOT test	number	378445127119
Result		✓ Passed
Advice	Rear Rear subframe corroded	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	



MOT #11	2021-09-02 08:58
MOT test number	136135925454
Result	🗙 Failed
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Rear Subframe corroded	
Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Advice Offside Front Coil spring corroded (5.3.1 (b) (i))	

MOT #10	2020-08-27 08:00
MOT test number	189970925099
Result	✓ Passed

MOT #9	2019-09-06 14:05
MOT test number	869557781972
Result	✓ Passed
Minor Central Stop lamp(s) with a multiple light source up to 1/2 not function	ning (4.3.1 (a) (i))

MOT #8	2019-09-04 15:57	
MOT test number	119238799119	
Result	🗙 Failed	
Fail Offside Rear Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))		
Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning	g (4.3.1 (a) (i))	







MOT #7	2018-08-28 07:30
MOT test number	821969073917
Result	✓ Passed
MOT #6	2017-09-05 10:56
MOT test number	647334404865
Result	✓ Passed
Advice Front Brake pac	d(s) wearing thin (3.5.1g)
MOT #5	2016-09-05 12:30 392277587073
MOT test number	
Result	✓ Passed
Advice Nearside Front	Nail in tyre
Advice Nearside Front	tyre outer sidewall damaged
MOT #4	
MOT #4	2015-09-01 10:15 163608589123
Result	
Result	✓ Passed
MOT #3	2015-09-01 10:15
MOT test number	436783727212
Result	× Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
	Nearcide Front Type tread donth below requirements of 1 (mm (4.1.5.1)

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)





MOT #2	2014-09-03 15:21
MOT test number	229026044230
Result	✓ Passed
MOT #1	2013-06-13 10:30
MOT test number	929314063146
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	
Notice Engine covers fitted obscuring some components in the engine bay	



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 December 2024	Expires: 21 December 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	A.F.
Category	ante.
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-11
Last registration	2023-12-07
Complete history	See info



Registration #1	2010-06-11	7 mi
Registration #2	2013-06-13	28.057 mi
Registration #3	2014-09-03	37.472 mi
Registration #4	2015-09-01	43.198 mi
Registration #5	2015-09-01	43.198 mi
Registration #6	2016-09-05	50.510 mi
Registration #7	2017-09-05	54.729 mi
Registration #8	2018-08-28	58.391 mi
Registration #9	2019-09-04	63.190 mi
Registration #10	2019-09-06	63.190 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 ma





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1842 mm
Height	1345 mm
Length	4198 mm
Wheel base	2468 mm
Kerb weight	1415 kg
Max. allowed weight	1815 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	CDL 028138