



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T32 TDI SPORTLINE KOMBI
Colour	Black
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 kW / 143 HP / 178 BHP
Max. torque	400 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	42.2 mpg
Consumption combined	36.2 mpg
CO2 emission	205 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-10
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-15
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #9	2023-08-16 09:05
MOT test number	625799407890
Result	✓ Passed
Next expiry date	2024-08-15
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Tail box corroded

MOT #8	2022-08-04 08:51
MOT test number	973627833350
Result	✓ Passed

MOT #7	2021-07-13 14:01
MOT test number	789891805904
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2020-07-25 08:18**MOT test number** 913855529533**Result** ✓ Passed**MOT #5** 2019-04-13 08:35**MOT test number** 937913460969**Result** ✓ Passed**MOT #4** 2018-05-23 11:18**MOT test number** 793638310718**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Slight corrosion in exhaust system**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2017-04-05 14:50**MOT test number** 136228150912**Result** ✓ Passed**Advice** Offside Rear tyre nail in main tread**MOT #2** 2017-04-04 08:38**MOT test number** 720165191635**Result** ✗ Failed**Fail** Offside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)**Advice** Offside Rear tyre nail in main tread**Fail** Nearside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)



MOT #1	2016-04-29 15:18
MOT test number	727864912222
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
15 August 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	15 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-03
Last registration	2023-08-16
Complete history	<a href="#">See info</a>



Registration #1	2013-06-03	14 mi
Registration #2	2016-04-29	40.186 mi
Registration #3	2017-04-04	50.195 mi
Registration #4	2017-04-05	50.195 mi
Registration #5	2018-05-23	51.239 mi
Registration #6	2019-04-13	52.104 mi
Registration #7	2019-05-29	52.277 mi
Registration #8	2019-05-29	52.277 mi
Registration #9	2019-05-29	52.277 mi
Registration #10	2019-05-29	52.277 mi
Registration #11	2019-05-29	52.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2242 mm
Height	1969 mm
Length	4890 mm
Wheel base	367 mm
Kerb weight	2098 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4

Number of axles	2
Engine number	CFCA107401