





report date: 2024-03-28

### General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC CDTI ECOFLEX S/S
Colour	Grey
Year of manufacture	2014
Top speed	122 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-09-05

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MAGE	
NACAI	history
141()1	11151 OT V

MOT expiry date	2025-01-30
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	7
Total items failed	0

MOT #8	2024-01-31 14:55
MOT test number	105761284970
Result	✓ Passed
Next expiry date	2025-01-30

MOT #7	2	2024-01-29 10:50
MOT test	number	962543329362
Result		<b>×</b> Failed
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
DANGER	OUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #6	2023-01-06 10:14
MOT test number	797932778685
Result	✓ Passed
MOT #5	2021-09-08 15:07
MOT test number	494129146932
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



MOT #4 2020-09-01 11:35

MOT test number 699446864954

**Result** ✓ Passed

**Minor** Central Front Lower Windscreen damaged but not adversely affecting driver's view stone chip ok at time of test (3.2 (a) (i))

MOT #3 2019-09-07 10:48

**MOT test number** 683134677294

Result \( \sqrt{Passed} \)

Minor Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))

MOT #2 2018-09-08 08:10

**MOT test number** 472495004423

**Result** ✓ Passed

Advice Tyre worn close to legal limit/worn on edge wheel nuts not fully checked due to covers fitted (5.2.3 (e))

MOT #1 2017-09-09 08:53

**MOT test number** 858286645857

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	30 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

Date

**Category** 

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	
*********	
***************************************	
***************************************	
********	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Mumber of plates	,
Current registration	UK NE
Plate since	
Current registration	AIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-30
Last registration	2024-01-31
Complete history	See info



Registration #1	2014-09-30	11 mi
Registration #2	2017-09-09	32.912 mi
Registration #3	2018-09-08	41.941 mi
Registration #4	2019-09-07	50.471 mi
Registration #5	2020-09-01	55.190 mi
Registration #6		71.777 es
Registration #6 Registration #7		11.777 ea
-		1.77 m
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1518 kg
Max. allowed weight	2040 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	A1141184FWXX0075LVL

CarCheck.co.uk page 11/11