



RF57GYW

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT TDCI T220 L SWB P/V 75
Colour	Silver
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	175 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-09-07
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	28
Total items failed	20

MOT #18 2020-08-24 11:17

MOT test number 633100605468

Result ✓ Passed

Next expiry date 2021-09-07

- Advice** Both front to rear brake pipes
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #17 2019-08-27 10:42

MOT test number 114171951886

Result ✓ Passed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive sump (8.4.1 (a) (i))

**MOT #16**

2019-08-24 11:10

MOT test number

364721624364

Result

✗ Failed

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Brake pipe excessively corroded and offside front to rear's (1.1.11 (c))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Oil leak, but not excessive sump (8.4.1 (a) (i))

Fail Nearside Front Brake pipe excessively corroded and offside front (1.1.11 (c))

Fail Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill holed (6.1.1 (c) (i))

MOT #15

2018-08-24 15:28

MOT test number

163871708777

Result

✓ Passed

Advice Both sills corroded

MOT #14

2017-08-30 15:07

MOT test number

595679454712

Result

✓ Passed

Advice Brake pad(s) wearing thin (3.5.1g)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Vehicle structure has slight corrosion underside vehicle (6.1.B.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #13** 2016-09-08 12:49**MOT test number** 590078333422**Result** ✓ Passed**MOT #12** 2016-09-08 12:03**MOT test number** 162839959950**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Offside Rear Nail in tyre**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #11** 2015-09-04 10:55**MOT test number** 984762806404**Result** ✓ Passed**Advice** Front Anti-roll bar has slight play in a ball joint Both (2.4.G.2)**MOT #10** 2015-09-04 10:55**MOT test number** 159927511453**Result** ✗ Failed**Pass with rectification** Rear Upper Stop lamp not working (1.2.1b)**Advice** Front Anti-roll bar has slight play in a ball joint Both (2.4.G.2)**MOT #9** 2014-09-02 16:33**MOT test number** 367795244214**Result** ✓ Passed

**MOT #8** 2014-09-02 10:26**MOT test number** 347455244260**Result** ✗ Failed**Fail** Nearside Rear Body has a sharp edge caused by corrosion (6.1.C.1)**Fail** Offside Front wheel bearing rough when rotated (2.5.A.2)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #7** 2013-11-04 13:35**MOT test number** 778708603314**Result** ✓ Passed**MOT #6** 2013-10-31 13:15**MOT test number** 475494203330**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**MOT #5** 2012-10-12 16:52**MOT test number** 786936182220**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside rear brake juddering slightly (3.7.A.5b)**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Nearside front wiper blade slightly smearing screen**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2012-10-11 12:15**MOT test number** 136955382248**Result** ✗ Failed**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Nearside front wiper blade slightly smearing screen**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside rear brake juddering slightly (3.7.A.5b)**MOT #3** 2011-10-28 10:45**MOT test number** 378361101396**Result** ✓ Passed**MOT #2** 2010-11-30 10:31**MOT test number** 493474330467**Result** ✓ Passed**MOT #1** 2010-11-30 09:52**MOT test number** 412224130362**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)



Tax & MOT check

✕
Untaxed

Tax expired:
31 October 2021

✕
MOT

Expired:
7 September 2021

Tax status	Expired at 31 October 2021
Days left	910 days too late
MOT expiry date	7 September 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	RF57GYW
Plate since	2019-03-28
Current registration	RF57GYW
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-30
Last registration	2020-08-24
Complete history	See info



Registration #1	2007-11-30	22 mi
Registration #2	2010-11-30	55.794 mi
Registration #3	2010-11-30	55.794 mi
Registration #4	2011-10-28	86.409 mi
Registration #5	2012-10-11	114.683 mi
Registration #6	2012-10-12	114.683 mi
Registration #7	2013-10-31	126.947 mi
Registration #8	2013-11-04	126.947 mi
Registration #9	2014-09-02	134.675 mi
Registration #10	2014-09-02	134.675 mi
Registration #11	2015-09-02	134.675 mi
Registration #12	2015-09-02	134.675 mi
Registration #13	2015-09-02	134.675 mi
Registration #14	2015-09-02	134.675 mi
Registration #15	2015-09-02	134.675 mi
Registration #16	2015-09-02	134.675 mi
Registration #17	2015-09-02	134.675 mi
Registration #18	2015-09-02	134.675 mi
Registration #19	2015-09-02	134.675 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1397 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	7T45626