



PEUGEOT




report date: 2022-08-08

General information

Make	PEUGEOT
Model	307 S
Colour	Blue
Year of manufacture	2003
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	169 g/km
CO2 label	H





MOT history

MOT expiry date	2024-03-09
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	100
Total items failed	18

MOT #25 2023-03-10 11:19

MOT test number 916310160238

Result ✓ Passed

Next expiry date 2024-03-09

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Side repeater slightly discoloured (4.4.3 (a))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #24 2022-03-08 14:23

MOT test number 741780521674

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #23**

2022-03-07 14:44

MOT test number

160844525036

Result**✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Nearside Rear Outer Brake pad(s) incorrectly mounted Lining detached from pad (1.1.13 (c))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #22**

2021-03-04 12:41

MOT test number

330210650545

Result**✓ Passed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))

**MOT #21**

2021-03-03 12:16

MOT test number

153122910068

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))**MAJOR** Rear Exhaust has a major leak of exhaust gases Back box (6.1.2 (a))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Wiper has split**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced x2 holes (6.1.1 (c) (i))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Front Wiper has split**MAJOR** Horn not working (7.7 (a) (ii))**MOT #20**

2020-03-05 17:57

MOT test number

696951708801

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2020-03-03 10:42

MOT test number

108155287852

Result**✗ Failed****MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))**MAJOR** Offside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MAJOR** Fuel pipe leaking (6.1.3 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))**MOT #18**

2019-03-08 17:53

MOT test number

363047703890

Result**✓ Passed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Coolant leak

**MOT #17**

2019-03-07 15:06

MOT test number

483324625948

Result**✗ Failed****Advice** Coolant leak**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases box (6.1.2 (a))**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Nearside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively split (3.4 (b) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))**MOT #16**

2018-02-13 13:12

MOT test number

259877780805

Result**✓ Passed****Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #15**

2018-02-09 14:58

MOT test number

382117338103

Result

✗ Failed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Offside Front wheel bearing has excessive play (2.5.A.3c)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Front registration plate letter/figure missing (6.3.1c)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm inner edge to canvas (4.1.E.1)

MOT #14

2017-02-06 13:17

MOT test number

420113236107

Result

✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' stone chip (8.3.1d)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Corrosion to both rear chassis rails where rear spring top mounts locate
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Play in steering rack inner joint(s)
- Advice** Nearside front tyre wearing on edges

**MOT #13**

2017-02-01 10:29

MOT test number

341996855356

Result

✗ Failed

- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Fail** Emissions not tested due to exhaust blow (7.3.A.1)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Advice** Corrosion to both rear chassis rails where rear spring top mounts locate
- Fail** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)
- Advice** Play in steering rack inner joint(s)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Exhaust has a major leak of exhaust gases front pipe where lambda sensor fits (7.1.2)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' stone chip (8.3.1d)
- Advice** Nearside front tyre wearing on edges
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Rear Seat belt anchorage prescribed area is excessively corroded outer sill area (5.2.6)

MOT #12

2016-02-03 09:39

MOT test number

856491275997

Result

✓ Passed

- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)

**MOT #11** 2015-01-12 12:17**MOT test number** 676102515098**Result** ✓ Passed**MOT #10** 2014-01-09 09:30**MOT test number** 108649104449**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #9** 2014-01-07 11:38**MOT test number** 606507304092**Result** ✗ Failed**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside front brake excessively fluctuating (3.7.B.3)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Horn not working (1.6.2a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2013-01-08 10:54**MOT test number** 397728503077**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #7	2012-01-12 09:51
---------------	------------------

MOT test number	958652112094
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2011-06-30 14:59
---------------	------------------

MOT test number	397571481157
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2010-07-01 17:16
---------------	------------------

MOT test number	794182580154
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---

Advice	Centre Front Exhaust has a minor leak of exhaust gases (7.1.2)
---------------	--

MOT #4	2009-07-01 14:58
---------------	------------------

MOT test number	223882389494
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-07-03 16:45
---------------	------------------

MOT test number	542105288188
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-07-02 11:34
---------------	------------------

MOT test number	460443787148
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2006-07-04 09:42
---------------	------------------

MOT test number	493915186161
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✗
MOT

Expired:
9 March 2024

Tax status

Valid until 1 August

Days left

96

MOT expiry date

9 March 2024

Full MOT history[See MOT history](#)

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	EXAMPLE
Category	EXAMPLE
Type	EXAMPLE



Damage 2

Date	EXAMPLE
Category	EXAMPLE
Type	EXAMPLE

Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-09-29
Current registration	 XXXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-09-30
Last registration	2023-03-10
Complete history	See info



Registration #1	2003-09-30	8 mi
Registration #2	2006-07-04	32.101 mi
Registration #3	2007-07-02	38.575 mi
Registration #4	2008-07-03	45.548 mi
Registration #5	2009-07-01	51.979 mi
Registration #6	2010-07-01	58.541 mi
Registration #7	2011-06-30	64.901 mi
Registration #8	2012-01-12	66.082 mi
Registration #9	2013-01-08	71.226 mi
Registration #10	2014-01-07	76.459 mi
Registration #11	2014-01-09	76.485 mi
Registration #12	2015-01-12	81.572 mi
Registration #13	2016-02-03	86.320 mi
Registration #14	2016-02-03	86.320 mi
Registration #15	2016-02-03	86.320 mi
Registration #16	2016-02-03	86.320 mi
Registration #17	2016-02-03	86.320 mi
Registration #18	2016-02-03	86.320 mi
Registration #19	2016-02-03	86.320 mi
Registration #20	2016-02-03	86.320 mi
Registration #21	2016-02-03	86.320 mi
Registration #22	2016-02-03	86.320 mi
Registration #23	2016-02-03	86.320 mi
Registration #24	2016-02-03	86.320 mi
Registration #25	2016-02-03	86.320 mi
Registration #26	2016-02-03	86.320 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1193 kg
Max. allowed weight	1693 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

Engine number

FX3V1925324