



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE TDI 100BHP
Colour	Silver
Year of manufacture	2009
Top speed	111 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-14
Pictures	14
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-14
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	16
Total items failed	7

MOT #18	2024-03-15 16:41
MOT test number	374878781931
Result	✓ Passed
Next expiry date	2025-03-14
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17	2024-03-07 16:33
MOT test number	865814038511
Result	✗ Failed
Fail	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16	2023-03-06 16:10
MOT test number	320482442997
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2023-02-27 15:55**MOT test number** 488019294454**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2021-09-28 14:57**MOT test number** 766554396351**Result** ✓ Passed**MOT #13** 2021-04-13 11:59**MOT test number** 508729694761**Result** ✓ Passed**MOT #12** 2021-04-13 11:59**MOT test number** 343622645339**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #11** 2020-07-09 08:28**MOT test number** 272115040930**Result** ✓ Passed**MOT #10** 2019-04-18 08:15**MOT test number** 446260133205**Result** ✓ Passed

**MOT #9** 2018-04-20 09:13**MOT test number** 314944635191**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-04-28 13:51**MOT test number** 962906344249**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-04-26 15:00**MOT test number** 394313907003**Result** ✗ Failed**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Mechanical brake component has restricted free movement (3.5.1k)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-04-27 09:23**MOT test number** 715880817324**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-05-01 15:16**MOT test number** 768401325132**Result** ✓ Passed

**MOT #4** 2015-05-01 14:00**MOT test number** 296801725198**Result** ✗ Failed**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #3** 2014-11-29 10:12**MOT test number** 409733034470**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-10-28 12:12**MOT test number** 918861903393**Result** ✓ Passed**MOT #1** 2012-11-27 16:41**MOT test number** 798722132313**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
14 March 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	YP59WWU
Plate since	2019-09-29
Current registration	YP59WWU
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-27
Last registration	2024-03-15
Complete history	See info



Registration #1	2009-11-27	9 mi
Registration #2	2012-11-27	28.051 mi
Registration #3	2013-10-28	38.954 mi
Registration #4	2014-11-29	53.760 mi
Registration #5	2015-05-01	56.971 mi
Registration #6	2015-05-01	56.971 mi
Registration #7	2016-04-27	65.926 mi
Registration #8	2017-04-26	75.274 mi
Registration #9	2017-04-28	75.274 mi
Registration #10	2018-04-20	85.068 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi
Registration #17	2019-05-20	95.277 mi
Registration #18	2019-05-20	95.277 mi
Registration #19	2019-05-20	95.277 mi
Registration #20	2019-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1370 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BSW 020646