





report date: 2024-03-29

General information

| Make | VOLVO |
|---------------------|----------------|
| Model | V50 D DRIVE SE |
| Colour | Black |
| Year of manufacture | 2012 |
| Top speed | 121 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 113 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 54.3 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 6.6 mpg |
| CO2 emission | 99 g/km |
| CO2 label | А |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

| Date | 2021-09-20 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk

Entry 1

| Date | 2021-09-14 |
|---------------|-------------|
| Pictures | 1 |
| Listing price | View report |



source: cargurus.co.uk

CarCheck.co.uk page 2/12



EN12KKW report date: 2024-03-29

MOT history

| MOT expiry date | 2025-01-11 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 10 |
| Failed MOT tests | 2 |
| Total advice items | 7 |
| Total items failed | 2 |

| MOT #12 | | 2024-01-09 14:58 |
|-----------|--|------------------|
| MOT test | number | 981982000603 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-01-11 |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice | Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #11 | 2023-01-10 10:37 |
|---|------------------|
| MOT test number | 553429255208 |
| Result | ✓ Passed |
| Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) | |

| MOT #10 | 2022-01-12 16:52 |
|-----------------|------------------|
| MOT test number | 702441003782 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



MOT #3

Result

MOT test number

EN12KKW

report date: 2024-03-29

2016-06-20 11:58

223847222318

✓ Passed

| MOT #9 | 2021-05-19 08:45 |
|--|------------------|
| MOT test number | 436022175147 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2020-05-13 08:22 |
| MOT test number | 401322789389 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2019-05-02 16:31 |
| MOT test number | 110851887511 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2019-05-02 10:57 |
| MOT test number | 894960356512 |
| Result | ★ Failed |
| Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |
| | |
| MOT #5 | 2018-05-23 11:46 |
| MOT test number | 819618115974 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2017-06-13 10:39 |
| MOT test number | 484558958716 |
| Result | ✓ Passed |
| | |

CarCheck.co.uk page 4/12



report date: 2024-03-29



 MOT #1
 2015-06-29 11:28

 MOT test number
 606500585159

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 277 |
| MOT expiry date | 11 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

EN12KKW

More info >

report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLVO had different number plates. about of pliates

CarCheck.co.uk page 9/12



EN12KKW report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2012-06-29 |
| Last registration | 2024-01-09 |
| Complete history | See info |



| Registration #1 | 2012-06-29 | 13 mi |
|------------------|------------|-----------|
| Registration #2 | 2015-06-29 | 28.270 mi |
| Registration #3 | 2016-06-20 | 33.499 mi |
| Registration #4 | 2016-06-20 | 33.499 mi |
| Registration #5 | 2017-06-13 | 36.669 mi |
| Registration #6 | 2018-05-23 | 39.650 mi |
| Registration #7 | 2019-05-02 | 42.487 mi |
| Registration #8 | 2019-05-02 | 42.487 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 9.70 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.70 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1770 mm |
|---------------------|---------|
| Height | 1457 mm |
| Length | 4522 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1433 kg |
| Max. allowed weight | 1900 kg |

Additional information

| Fuel tank capacity | 52 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

Number of axles2Engine number2041867