



report date: 2024-03-28

General information

Make	MAZDA
Model	3 D SE AC
Colour	Red
Year of manufacture	-
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg



LABEL UNKNOWN

**MOT history**

MOT #14	2020-08-07 16:26
MOT test number	541213843375
Result	✓ Passed
Next expiry date	2021-08-13
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced inner sills and floor (6.1.1 (c) (i))

MOT #13	2020-08-07 13:24
MOT test number	437292154227
Result	✗ Failed
MAJOR	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
Advice	Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced inner sills and floor (6.1.1 (c) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))

**MOT #12**

2019-08-13 11:27

MOT test number

910392602088

Result

✓ Passed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11

2018-08-14 13:13

MOT test number

965750461687

Result

✓ Passed

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

MOT #10

2017-09-20 15:03

MOT test number

219236052705

Result

✓ Passed

Advice

Engine management lamp on

MOT #9

2017-09-20 15:03

MOT test number

639565674656

Result

✗ Failed

Advice

Engine management lamp on

Pass with rectification

Offside Stop lamp not working (1.2.1b)

Pass with rectification

Nearside Headlamp aim too low (1.8)

Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)

**MOT #8** 2016-08-25 12:55**MOT test number** 125848774510**Result** ✓ Passed

- Advice** Nearside Front mirror glass cracked
- Advice** Engine management lamp on at time of test
- Advice** Nearside Rear Nail in tyre

MOT #7 2016-08-25 12:55**MOT test number** 988217545429**Result** ✗ Failed

- Pass with rectification** Offside Headlamp aim too low (1.8)
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Advice** Engine management lamp on at time of test
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front mirror glass cracked

MOT #6 2015-08-29 09:35**MOT test number** 594740172098**Result** ✓ Passed**MOT #5** 2015-08-29 09:35**MOT test number** 730939242674**Result** ✗ Failed

- Pass with rectification** Offside Headlamp aim too high (1.8)
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2014-08-29 15:28**MOT test number** 338241244461**Result** ✓ Passed**MOT #3** 2014-08-29 11:35**MOT test number** 855331544215**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-08-08 11:42**MOT test number** 427520923266**Result** ✓ Passed**MOT #1** 2012-11-12 12:44**MOT test number** 597487212382**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-11-19
Last registration	2020-08-07
Complete history	See info



Registration #1	2009-11-19	24 mi
Registration #2	2012-11-12	45.357 mi
Registration #3	2013-08-08	53.129 mi
Registration #4	2014-08-29	59.036 mi
Registration #5	2014-08-29	59.038 mi
Registration #6	2015-08-29	63.982 mi
Registration #7	2015-08-29	63.982 mi
Registration #8	2016-08-25	70.906 mi
Registration #9	2016-08-25	70.906 mi
Registration #10	2016-08-25	70.906 mi
Registration #11	2016-08-25	70.906 mi
Registration #12	2016-08-25	70.906 mi
Registration #13	2016-08-25	70.906 mi
Registration #14	2016-08-25	70.906 mi
Registration #15	2016-08-25	70.906 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4415 mm
Max. allowed weight	1825 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	Y6 294254