





report date: 2024-03-29

### General information

Make	VAUXHALL
Model	VECTRA VVT LIFE
Colour	Blue
Year of manufacture	2008
Top speed	123 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

### Entry 1

Date 2021-06-13

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



2022-12-22 15:02

MOT history

MOT #14

MOT expiry date	2025-01-04
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	17
Total items failed	4

MOT #16	2024-01-05 08:50
MOT test number	151941151433
Result	✓ Passed
Next expiry date	2025-01-04

MOT #15	2024-01-05 08:50
MOT test number	411632835915
Result	<b>X</b> Failed
Pass with rectification	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT test number	228030544691
Result	<b>✓</b> Passed
MOT #13	2021-12-17 15:18
MOT test number	522448670480
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #12** 2020-10-31 13:15

MOT test number 142564626608

**Result** ✓ Passed

Advice Offside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement d (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement d (5.3.4 (a) (i))

**MOT #11** 2019-05-11 11:44

**MOT test number** 503436418444

Advice Front Exhaust has a minor leak of exhaust gases pipe (6.1.2 (a))

**MOT #10** 2019-05-10 15:13

**MOT test number** 841926954097

**Result** X Failed

**Fail** Front Brake pipe excessively corroded to rear (1.1.11 (c))

**Advice** Front Exhaust has a minor leak of exhaust gases pipe (6.1.2 (a))

MOT #9 2018-05-15 15:45

MOT test number 747490142150

Result \rightarrow Passed

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Brake pipe slightly corroded Both front to rear brake pipes (3.6.B.2c)

**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Brake pipe slightly corroded From flexi hose to rear brake caliper (3.6.B.2c)

CarCheck.co.uk page 4/13



MOT #8 2017-11-13 13:04

MOT test number 699827485244

**Result** ✓ Passed

**Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)

**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #7** 2017-11-13 09:39

MOT test number 123833481001

**Result** X Failed

Fail Offside Rear coil spring broken (2.4.C.1a)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)

**Fail** Offside Front coil spring broken (2.4.C.1a)

**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)

MOT #6 2016-11-07 10:57

MOT test number 440226476209

**Result** ✓ Passed

MOT #5 2015-11-20 09:52

**MOT test number** 900770469824

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #4	2014-11-12 10:27
MOT test number	136966014349
Result	<b>✓</b> Passed
MOT #3	2013-11-06 09:03
MOT test number	955500013321
Result	<b>✓</b> Passed
MOT #2	2012-11-16 09:07
MOT test number	647861622349
Result	<b>✓</b> Passed
MOT #1	2011-11-16 09:01
MOT test number	195500621359
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	4 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	

**Type** 

Damage 2

**Date** 

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	
***************************************	
*******	
***************************************	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	Moro info

CarCheck.co.uk page 10/13



### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-03
Last registration	2024-01-05
Complete history	See info



Registration #1	2008-12-03	23 mi
Registration #2	2011-11-16	33.490 mi
Registration #3	2012-11-16	40.782 mi
Registration #4	2013-11-06	47.749 mi
Registration #5	2014-11-12	55.349 mi
Registration #6	2015-11-20	64.081 mi
Registration #7	2016-11-07	70.044 mi
Registration #8	2017-11-13	76.027 mi
Registration #9	2017-11-13	76.027 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		111,7177 aug

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4824 mm
Wheel base	2830 mm
Kerb weight	1400 kg
Max. allowed weight	2030 kg

## Additional information

Fuel tank capacity	61
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20LS0295

CarCheck.co.uk page 13/13