



**BF08GFK**

report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Gold
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Sequential

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 2

Date	2021-07-31
Pictures	45
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-03
Pictures	45
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-07-04
<b>MOT pass rate</b>	71 %
<b>MOT passed</b>	15
<b>Failed MOT tests</b>	6
<b>Total advice items</b>	31
<b>Total items failed</b>	6

<b>MOT #21</b>	2023-07-05 16:06
<b>MOT test number</b>	309490603716
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-07-04

<b>MOT #20</b>	2022-06-29 08:48
<b>MOT test number</b>	436897297568
<b>Result</b>	✓ Passed

<b>MOT #19</b>	2022-06-10 09:54
<b>MOT test number</b>	526205362519
<b>Result</b>	✓ Passed
<b>Advice</b>	General under body corrosion

<b>MOT #18</b>	2021-07-02 16:19
<b>MOT test number</b>	241100458559
<b>Result</b>	✓ Passed

<b>MOT #17</b>	2020-10-24 11:41
<b>MOT test number</b>	942426720394
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2020-10-24 11:41**MOT test number** 763750396031**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #15** 2019-09-28 13:53**MOT test number** 871130795546**Result** ✓ Passed**MOT #14** 2019-09-28 12:17**MOT test number** 430492690984**Result** ✗ Failed**MAJOR** Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**MOT #13** 2018-09-26 14:54**MOT test number** 418749453326**Result** ✓ Passed**Advice** Nearside Rear Inner Road wheel slightly distorted rim (5.2.2 (c) (i))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened faces (1.1.14 (a) (ii))

**MOT #12**

2018-09-26 09:56

**MOT test number**

743732756697

**Result****✗ Failed****Advice**

Nearside Rear Inner Road wheel slightly distorted rim (5.2.2 (c) (i))

**Advice**

Offside Front Play in steering rack inner joint(s)

**Advice**

Front Inner Brake disc worn, pitted or scored, but not seriously weakened faces (1.1.14 (a) (ii))

**MAJOR**

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Advice**

Nearside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))

**MOT #11**

2017-10-18 10:59

**MOT test number**

303909873660

**Result****✓ Passed****Advice**

Nearside Rear tyre outer side wall wearing

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened both on inner faces (3.5.1i)

**MOT #10**

2017-10-11 12:39

**MOT test number**

912967272832

**Result****✗ Failed****Fail**

Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened both on inner faces (3.5.1i)

**Advice**

Nearside Rear tyre outer side wall wearing

**MOT #9**

2016-10-10 09:38

**MOT test number**

903362863875

**Result****✓ Passed**

**MOT #8** 2015-10-15 10:32**MOT test number** 781078302932**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both inner faces (3.5.1i)**MOT #7** 2015-10-12 14:46**MOT test number** 819446670344**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords wall (4.1.D.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both inner faces (3.5.1i)**MOT #6** 2014-10-15 11:50**MOT test number** 979098984229**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2014-10-15 10:31**MOT test number** 886548484214**Result** ✗ Failed**Fail** Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Anti-roll bar linkage damaged and seriously weakened (2.4.G.1)

**MOT #4** 2013-10-09 11:30**MOT test number** 779912883217**Result** ✓ Passed**Notice** Items hanging from rear view mirror NOT in drivers view of the road**Notice** DSC de-activated for RBT**MOT #3** 2012-10-17 15:00**MOT test number** 905871692272**Result** ✓ Passed**MOT #2** 2012-03-27 10:44**MOT test number** 609647082053**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #1** 2011-03-14 10:43**MOT test number** 745623771037**Result** ✓ Passed**Notice** Both rear shock absorbers very slight dampness.



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
4 July 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	4 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2008-04-05
Last registration	2023-07-05
Complete history	<a href="#">See info</a>



Registration #1	2008-04-05	12 mi
Registration #2	2011-03-14	21.948 mi
Registration #3	2012-03-27	29.759 mi
Registration #4	2012-10-17	32.906 mi
Registration #5	2013-10-09	37.744 mi
Registration #6	2014-10-15	43.084 mi
Registration #7	2014-10-15	43.084 mi
Registration #8	2015-10-12	47.291 mi
Registration #9	2015-10-15	47.307 mi
Registration #10	2016-10-10	51.558 mi
Registration #11	2017-10-11	55.351 mi
Registration #12	2017-10-18	55.417 mi
Registration #13	2018-05-22	55.557 mi
Registration #14	2018-05-22	55.557 mi
Registration #15	2018-05-22	55.557 mi
Registration #16	2018-05-22	55.557 mi
Registration #17	2018-05-22	55.557 mi
Registration #18	2018-05-22	55.557 mi
Registration #19	2018-05-22	55.557 mi
Registration #20	2018-05-22	55.557 mi
Registration #21	2018-05-22	55.557 mi
Registration #22	2018-05-22	55.557 mi
Registration #23	2018-05-22	55.557 mi
Registration #24	2018-05-22	55.557 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	080212203227BG