



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D S
Colour	Blue
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	153 g/km
CO2 label	G



**MOT history**

MOT expiry date	2021-09-02
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	32
Total items failed	7

MOT #14	2020-09-03 15:06
MOT test number	338658084908
Result	✓ Passed
Next expiry date	2021-09-02
Advice	Offside Front steering rack gaiter deteriorated

MOT #13	2019-05-21 14:58
MOT test number	692467808963
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2019-05-17 13:31**MOT test number** 276215917770**Result** ✗ Failed

- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Rear Anti-roll bar linkage ball joint excessively worn both (5.3.4 (a) (i))
- MAJOR** Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Rear Service brake excessively fluctuating (1.2.1 (e))

MOT #11 2018-05-14 16:22**MOT test number** 431947804017**Result** ✓ Passed

- Advice** Manufacturer's engine and body covers fitted restricting inspection of components
- Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #10 2017-04-14 12:46**MOT test number** 595853128462**Result** ✓ Passed

- Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Steering rack gaiter deteriorated (2.2.D.2d)

**MOT #9** 2016-04-18 16:20**MOT test number** 410551607490**Result** ✓ Passed**Advice** Nearside Rear Tie bar/rod has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tie bar/rod has slight play in a ball joint (2.4.G.2)**MOT #8** 2015-04-09 19:10**MOT test number** 919429595021**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-04-09 16:03**MOT test number** 418459295036**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-03-27 07:14**MOT test number** 639286784072**Result** ✓ Passed

**MOT #5** 2013-04-03 12:58**MOT test number** 638293293036**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear exhaust box rusty**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2013-04-03 12:58**MOT test number** 867533293028**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Notice** Rear exhaust box rusty**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2012-03-09 17:02**MOT test number** 407899162017**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2011-03-15 16:21**MOT test number** 407544371096**Result** ✓ Passed



MOT #1	2011-03-15 16:21
MOT test number	227064471041
Result	✗ Failed
Pass with rectification	Nearside Rear Fluid suspension unit leaking (2.4.D.2)
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

X

Untaxed

Tax expired:
30 April 2021

X

MOT

Expired:
2 September 2021

Tax status	Expired at 30 April 2021
Days left	1094 days too late
MOT expiry date	2 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BT57YPC
Plate since	2019-03-28
Current registration	BT57YPC
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2007-12-05
Last registration	2020-09-03
Complete history	See info



Registration #1	2007-12-05	26 mi
Registration #2	2011-03-15	74.301 mi
Registration #3	2012-03-09	85.319 mi
Registration #4	2013-04-03	96.055 mi
Registration #5	2014-03-27	108.715 mi
Registration #6	2015-04-09	128.525 mi
Registration #7	2015-04-09	128.525 mi
Registration #8	2015-04-09	128.525 mi
Registration #9	2015-04-09	128.525 mi
Registration #10	2015-04-09	128.525 mi
Registration #11	2015-04-09	128.525 mi
Registration #12	2015-04-09	128.525 mi
Registration #13	2015-04-09	128.525 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	130531