





report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI GO
Colour	Black
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 2


Date	2021-07-06	
Pictures	0	
Listing price	<u>View report</u>	

source: autotrader.co.uk

Entry 1

Date	2021-06-26	
Pictures	5	
Listing price	<u>View report</u>	









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-04-05
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	10
Total items failed	2

MOT #10		2023-03-11 14:14
MOT test	number	656828007677
Result		✓ Passed
Next expiry date 2024-04-0		2024-04-05
Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #9		2022-04-05 15:57
MOT test	number	577299200470
Result		✓ Passed
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Central Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	.4 (a) (ii))

MOT #8	2021-04-06 15:58
MOT test number	507524083752
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #7 2021-04-06 15:58

MOT test number 902127981900

Result X Failed

Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively blade

torn (3.4 (b) (ii))

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively blade

torn (3.4 (b) (ii))

MOT #6 2020-03-18 14:57

MOT test number 439222146764

MOT #5 2020-03-16 12:23

MOT test number 171744470557

Result X Failed

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #4 2019-03-22 16:57

MOT test number 914209306567

Result

Passed

MOT #3 2019-03-22 14:37

MOT test number 334647692893

Result X Failed

DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Front Windscreen washer not working (3.5 (a))

Advice Rear brake discs damaged

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Brake lever has insufficient reserve travel (1.1.2 (a))

CarCheck.co.uk page 4/12



MOT #2	2018-04-03 14:42
MOT test number	445097765050

Result	✓ Passed
MOT #1	2017-10-02 12:15
MOT test number	958682617385
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	5 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HYUNDAI had different number plates.	,		
See in this check if this HYUNDAI had different number plates.			NDAI
See in this check if this HYUNDAI had different number plates.			
See in this check if this HYUNDAI had different number plates.			
See in this check if this HYUNDAI had different number plates.			
See in this check if this HYUNDAI had different number plates.			
See in this check if this HYUNDAI had different number plates.	********		
See in this check if this HYUNDAI had different number plates.			
See in this check if this HYUNDAI had different number plates.	***************************************		
See in this check if this HYUNDAI had different number plates.		More info	>
器 UK	Plate changes		
器 UK	See in this check if this HYUNDAI had different number plates.		
器 UK	Number of plates		
Platte since	Current registration	UK NE	
Platte since	Plate since		
More info >	Current registration	UK NE	
More info >	Plate since		
		More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-08-18
Last registration	2023-03-11
Complete history	See info



Registration #1	2014-08-18	7 mi
Registration #2	2017-10-02	24.571 mi
Registration #3	2018-04-03	28.256 mi
Registration #4	2019-03-22	49.836 mi
Registration #5	2019-03-22	49.836 mi
Registration #6	2020-03-16	62.239 mi
Registration #7	2020-03-18	62.268 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71.777 mg

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

D4FDEZ280515