



T232BLR

report date: 2024-03-28

General information

Make	BMW
Model	Z3
Colour	Black
Year of manufacture	1999
Gearbox	-

Engine & fuel consumption

Engine capacity	1.991 cc
Fuel type	Petrol




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-06
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-29
MOT pass rate	60 %
MOT passed	18
Failed MOT tests	12
Total advice items	50
Total items failed	30

MOT #30	2023-10-30 11:25
MOT test number	549373542046
Result	✓ Passed
Next expiry date	2024-10-29

MOT #29	2022-05-17 08:54
MOT test number	647905266085
Result	✓ Passed
Advice	Rear Brake disc worn, but not excessively Both Sides (1.1.14 (a) (i))
Advice	Front Brake disc worn, but not excessively Both Sides (1.1.14 (a) (i))

MOT #28	2022-05-16 09:46
MOT test number	362319566120
Result	✗ Failed
Advice	Rear Brake disc worn, but not excessively Both Sides (1.1.14 (a) (i))
Advice	Front Brake disc worn, but not excessively Both Sides (1.1.14 (a) (i))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #27**

2021-05-06 11:28

MOT test number

852785862467

Result

✓ Passed

- Advice** Offside Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Tyre slightly cracking or perishing in tread (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Tyre slightly cracking or perishing in tread (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive Slight Leak from transmission gear box (8.4.1 (a) (i))
- Advice** Engine covers and under trays fitted obscuring some underside components

MOT #26

2021-04-30 10:05

MOT test number

422054954616

Result

✗ Failed

- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Engine covers and under trays fitted obscuring some underside components
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Tyre slightly cracking or perishing in tread (5.2.3 (d) (ii))
- Fail** Headlamp aim not tested Both dipped beams not working (4.1.2 (b))
- Advice** Oil leak, but not excessive Slight Leak from transmission gear box (8.4.1 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Tyre slightly cracking or perishing in tread (5.2.3 (d) (ii))

**MOT #25**

2020-04-14 11:32

MOT test number

386437032398

Result

✓ Passed

Advice Engine covers and under trays fitted obscuring some underside components**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** All brake discs corroded**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Play in steering rack inner joint(s)**MOT #24**

2020-04-14 11:32

MOT test number

835815409296

Result

✗ Failed

Advice Engine covers and under trays fitted obscuring some underside components**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Play in steering rack inner joint(s)**Pass with rectification** Nearside Front Windscreen wiper blade missing (3.4 (b) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** All brake discs corroded**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Front Windscreen wiper blade missing (3.4 (b) (ii))**MOT #23**

2019-03-26 15:03

MOT test number

348979918374

Result

✓ Passed

Advice Engine covers and under trays obscuring some components

**MOT #22**

2019-03-15 14:32

MOT test number

107392085201

Result**✗ Failed****Fail**

Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.5 (b) (i))

Fail

Nearside Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))

FailNearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
225 / 50 zr 16 92 w (5.2.3 (d) (i))**Advice**

Engine covers and under trays obscuring some components

Minor

Rear fog lamp switch not operating in accordance with the requirements (4.5.3 (a) (i))

MOT #21

2018-04-03 08:06

MOT test number

112302742390

Result**✓ Passed****Advice**

Offside Front Bumper insecure

Advice

Nearside Rear tyre excessively perished

Advice

Offside Rear Bumper insecure

**MOT #20**

2018-03-26 08:42

MOT test number

253829752100

Result**✗ Failed**

- Fail** Offside Front Headlamp insecure (1.7.3)
- Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)
- Fail** Offside Rear Rear reflector excessively damaged so that its function is impaired (1.5.1c)
- Fail** Rear registration plate deteriorated (6.3.1d)
- Advice** Offside Rear Bumper insecure
- Fail** Offside Front Front position lamp(s) missing (1.1.A.3a)
- Fail** Rear fog lamp switch faulty (1.3.1a)
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail** Front registration plate deteriorated (6.3.1d)
- Advice** Nearside Rear tyre excessively perished
- Advice** Offside Front Bumper insecure
- Fail** Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #19

2017-03-11 11:46

MOT test number

655500114649

Result**✓ Passed****MOT #18**

2017-03-11 11:45

MOT test number

527258704510

Result**✗ Failed**

- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)
- Pass with rectification** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**MOT #17** 2017-03-07 11:22**MOT test number** 621234466604**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #16** 2016-06-23 11:26**MOT test number** 136271270023**Result** ✓ Passed**MOT #15** 2016-06-23 11:26**MOT test number** 819543310378**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #14** 2015-06-08 16:07**MOT test number** 436349155167**Result** ✓ Passed**MOT #13** 2015-06-08 14:39**MOT test number** 269049455136**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #12** 2014-06-27 10:39**MOT test number** 775518674121**Result** ✓ Passed**Notice** Nearside and offside front tyres are cracking outer shoulders

**MOT #11** 2013-06-20 08:34**MOT test number** 526161573183**Result** ✓ Passed**Notice** N/s/f and o/s/f tyre perished inner/outer sidewalls**MOT #10** 2013-06-17 15:29**MOT test number** 435878963124**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Notice** N/s/f and o/s/f tyre perished inner/outer sidewalls**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #9** 2012-06-15 15:32**MOT test number** 995577162186**Result** ✓ Passed**Notice** Offside front tyre perishing outer edge & between thread**Notice** Offside rear tyre perishing outer edge.& wall & between thread**Notice** Nearside front tyre perishing between thread & outer edge**MOT #8** 2011-06-03 11:17**MOT test number** 609324551184**Result** ✓ Passed**Notice** Offside front and offside rear tyres cracked.**MOT #7** 2010-06-11 15:28**MOT test number** 801982960117**Result** ✓ Passed**Notice** Offside rear tyre cracking up

**MOT #6** 2010-06-09 10:10**MOT test number** 234280460124**Result** ✗ Failed**Notice** Offside rear tyre cracking up**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #5** 2009-06-09 16:40**MOT test number** 112960269143**Result** ✓ Passed**Notice** Offside front and offside rear tyres cracking up**MOT #4** 2009-06-08 10:22**MOT test number** 834329059193**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Offside front and offside rear tyres cracking up**MOT #3** 2008-06-26 09:11**MOT test number** 282128678141**Result** ✓ Passed**Notice** Front grill damage**MOT #2** 2007-06-13 11:39**MOT test number** 772144067149**Result** ✓ Passed**Notice** Front discs have surface rust



MOT #1	2006-06-29 10:25
MOT test number	504300586173
Result	✓ Passed



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	32
First mileage registration	1999-12-31
Last registration	2023-10-30
Complete history	See info



Registration #1	1999-12-31	7 mi
Registration #2	2006-06-29	10.474 mi
Registration #3	2007-06-13	10.727 mi
Registration #4	2008-06-26	12.883 mi
Registration #5	2009-06-08	13.442 mi
Registration #6	2009-06-09	13.457 mi
Registration #7	2010-06-09	14.324 mi
Registration #8	2010-06-11	14.324 mi
Registration #9	2011-06-03	15.487 mi
Registration #10	2012-06-15	16.789 mi
Registration #11	2013-06-17	18.164 mi
Registration #12	2013-06-20	18.175 mi
Registration #13	2014-06-27	18.217 mi
Registration #14	2015-06-08	18.234 mi
Registration #15	2015-06-08	18.236 mi
Registration #16	2016-06-23	18.248 mi
Registration #17	2016-06-23	18.248 mi
Registration #18	2016-06-23	18.248 mi
Registration #19	2016-06-23	18.248 mi
Registration #20	2016-06-23	18.248 mi
Registration #21	2016-06-23	18.248 mi
Registration #22	2016-06-23	18.248 mi
Registration #23	2016-06-23	18.248 mi
Registration #24	2016-06-23	18.248 mi
Registration #25	2016-06-23	18.248 mi
Registration #26	2016-06-23	18.248 mi

Registration #27	2025-25-25	25,252 442
Registration #28	2025-25-25	25,252 442
Registration #29	2025-25-25	25,252 442
Registration #30	2025-25-25	25,252 442
Registration #31	2025-25-25	25,252 442
Registration #32	2025-25-25	25,252 442

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Engine number NOT KNOWN