





report date: 2024-03-28

#### General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	White
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

### Internet history

#### Entry 2

Date 2021-10-10

Pictures 39

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-10-09
Pictures	39

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

✓ Passed

### **MOT** history

Result

MOT expiry date	2024-10-05
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	14
Total items failed	3

MOT #15	2023-10-02 09:56
MOT test number	206866617750
Result	✓ Passed
Next expiry date	2024-10-05
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14	2022-10-05 13:53
MOT test number	603538984002
Result	<b>✓</b> Passed
MOT #13	2021-10-06 15:24
MOT test number	809182384506

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Pass with rectification

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10

MOT test number

Result

Advice Both rear tyre heavily perished and deep cracks in treads

2019-04-18 10:20

839347561798

✓ Passed

MOT #9 2018-04-16 11:12

MOT test number 496977624914

Result ✓ Passed

MOT test number

Result

Advice Offside Rear (tyre) low on side of tyre (on 2mm )

Advice Offside Front Oil leak (gearbox) oil seal leaking on offside of gearbox

MOT #7

MOT test number

290360344221

Result

Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Front Windscreen washer provides insufficient washer liquid (8.2.3)

 MOT #5
 2015-11-02 16:01

 MOT test number
 782805724902

 Result
 ✓ Passed

 MOT #4
 2015-11-02 10:47

 MOT test number
 717292533838

 Result
 X Failed

 Fail

 Nearside Side repeater not working (1.4.A.2c)

MOT test number
625963494297

Result

Notice Nail in nearside rear tyre

Notice Nsf outer mirror glass missing

Notice Nsf wiper split but clears screen

 MOT #2
 2013-11-04 12:42

 MOT test number
 157008803349

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2012-10-09 09:41

**MOT test number** 515603582203

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	5 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

·		
For how long did the current and previous owner(s) have this TOYOTA? How many owners have? Check it in the premium report and see all owner registrations. Download the full re		OTA
********		
***************************************		
*************		
	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	NK NA	
Plate since		
Current registration	NK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-13
Last registration	2023-10-02
Complete history	See info



Registration #1	2009-11-13	24 mi
Registration #2	2012-10-09	22.493 mi
Registration #3	2013-11-04	31.586 mi
Registration #4	2014-10-20	42.557 mi
Registration #5	2015-11-02	50.119 mi
Registration #6	2015-11-02	50.119 mi
Registration #7	2016-04-19	53.984 mi
Registration #8	2016-04-19	53.984 mi
Registration #9	2017-04-12	59.149 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

## Additional information

Fuel tank capacity	32 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2

Engine number 1KR0891922