



General information

Make	VOLKSWAGEN
Model	GOLF SE TDI DSG
Colour	Blue
Year of manufacture	2009
Top speed	114 mph
0 - 60 mph	12.0 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





MOT history

MOT expiry date	2024-09-01
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	16
Total items failed	13

MOT #17	2023-08-15 16:22
MOT test number	714962516337
Result	✓ Passed
Next expiry date	2024-09-01
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2023-08-15 11:44
MOT test number	816518314029
Result	✗ Failed
Fail	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-08-16 15:44
MOT test number	235736988519
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2022-08-16 11:20**MOT test number** 204841679090**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Offside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))**MOT #13** 2021-08-11 11:49**MOT test number** 102184859325**Result** ✓ Passed**MOT #12** 2020-09-02 09:17**MOT test number** 245028993455**Result** ✓ Passed**Advice** Nearside Mirror glass missing**Advice** Items removed from driver's view prior to test rear view mirror

**MOT #11**

2020-09-01 09:09

MOT test number

844357569234

Result**✗ Failed****Fail**

Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail

Offside Rear Service brake excessively binding (1.2.1 (f))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Nearside Mirror glass missing

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Items removed from driver's view prior to test rear view mirror

Fail

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #10

2019-08-09 14:46

MOT test number

559746228134

Result**✓ Passed****MOT #9**

2019-08-09 11:33

MOT test number

205436564142

Result**✗ Failed****Pass with rectification**

Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail

Offside Headlamp aim too low (4.1.2 (a))

Fail

Nearside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

MOT #8

2018-08-10 13:00

MOT test number

427826137763

Result**✓ Passed**

**MOT #7** 2018-08-09 08:07**MOT test number** 271465058635**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick also binding (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2017-08-21 10:25**MOT test number** 668942296190**Result** ✓ Passed**Advice** Zero flow detected in smoke meter, results printout unavailable**MOT #5** 2016-12-02 11:06**MOT test number** 204076160745**Result** ✓ Passed**MOT #4** 2015-11-27 11:05**MOT test number** 331354533772**Result** ✓ Passed**MOT #3** 2014-11-12 15:41**MOT test number** 526286514304**Result** ✓ Passed**MOT #2** 2013-11-07 14:20**MOT test number** 917621113335**Result** ✓ Passed**Advice** Offside Rear Direction indicator has light sources not illuminating, but not more than 50% (1.4.A.2c)



MOT #1	2012-11-23 10:35
MOT test number	469978022306
Result	✓ Passed
<div>Advice</div> (1.4.A.2c)	Nearside Rear Direction indicator has light sources not illuminating, but not more than 50%



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
1 September 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-02
Last registration	2023-08-15
Complete history	See info



Registration #1	2009-12-02	7 mi
Registration #2	2012-11-23	18.248 mi
Registration #3	2013-11-07	25.232 mi
Registration #4	2014-11-12	30.284 mi
Registration #5	2015-11-27	34.671 mi
Registration #6	2016-12-02	37.327 mi
Registration #7	2017-08-21	39.838 mi
Registration #8	2018-08-09	48.462 mi
Registration #9	2018-08-10	48.466 mi
Registration #10	2019-08-09	50.000 mi
Registration #11	2019-08-09	50.000 mi
Registration #12	2019-08-09	50.000 mi
Registration #13	2019-08-09	50.000 mi
Registration #14	2019-08-09	50.000 mi
Registration #15	2019-08-09	50.000 mi
Registration #16	2019-08-09	50.000 mi
Registration #17	2019-08-09	50.000 mi
Registration #18	2019-08-09	50.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1592 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1399 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAY 136263